

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21012825/ETF3E2

**Date:** 05/04/2022

### REFERENCE

Insured/Claimant:	NG KEE SOON	Policy No:	1900129993		
Date of Loss:	17/12/2021	Nature of Claim:	OD	Claim No:	3405276599SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN4494D		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Engine No:	3A92UHT6491
Reg. Date:	13/08/2019 (Man. Year: 2019)	Chassis No:	MMBSTA13AKH002198
Colour:	White	Odometer:	20937 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$63,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,387.04	3,574.14	812.90	18.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,140.00	5,305.00	835.00	13.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,527.04</b>	<b>8,879.14</b>	<b>1,647.90</b>	<b>15.65</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>736.89</b>	<b>621.54</b>	<b>115.35</b>	<b>15.65</b>
<b>Nett Amount (S\$)</b>	<b>11,263.93</b>	<b>9,500.68</b>	<b>1,763.25</b>	<b>15.65</b>

### INSPECTION

Date of Assignment:	20/12/2021	
Date Inspected:	21/12/2021 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	9.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*20.00 FS
2	1		*BRACKET, RR BUMPER, LH	Not Necessary	28.00 FL	*- FL
3	1		*BRACKET, RR BUMPER, RH	Not Necessary	28.00 FL	*- FL
4	1		*FACE, RR BUMPER	Damaged	751.00 FL	*751.00 FL
5	1		*PANEL, RR END	Dented	427.00 FL	*427.00 FL
6	1		*WEATHERSTRIP, TRUNK LID	Crushed	157.00 FL	*157.00 FL
7	1		*PANEL, TRUNK LID	Dented	795.00 FL	*795.00 FL
8	1		*HINGE, TRUNK LID, RH	Not Necessary	203.00 FL	*- FL
9	1		*HINGE, TRUNK LID, LH	Not Necessary	203.00 FL	*- FL
10	1		*LATCH, TRUNK LID	Not Necessary	218.00 FL	*- FL
11	1		*STRIKER, TRUNK LID LATCH	Not Necessary	20.00 FL	*- FL
12	1		*MARK, THREE-DIA	Necessary	70.00 FL	*70.00 FL
13	1		*MARK, ATTRAGE	Necessary	21.00 FL	*21.00 FL
14	1		*TRIM, RR END	Crushed	66.00 FL	*66.00 FL
15	1		*BOARD, TRUNK ROOM FLOOR	Torn	195.00 FL	*195.00 FL
16	1		*CARPET TRUNK ROOM	Not Necessary	170.00 FL	*- FL
17	1		*UNPAINTED BODYKITS	Broken	1,643.00 FS	*1,643.00 FS
18	1		*SHARK FIN ANTENNA, ATTRAGE WHITE	Not Necessary	123.00 FS	*- FS
					<b>Sub Total (\$\$)</b>	<b>5,158.00      4,145.00</b>
					<b>- List Item Discount on L Items 23.00/23.00% (\$\$)</b>	<b>770.96      570.86</b>
					<b>Total Parts (\$\$)</b>	<b>4,387.04      3,574.14</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE REAR BUMPER, BOOT, END PANEL, BODY KIT & AFFECTED AREA. REPAIR ON REAR BOTH FENDER & FLOOR PANEL	New	3,150.00	2,475.00
2	PAINT WORK ON REAR BUMPER, BOOT, END PANEL, BOTH REAR FENDER, BODY KIT	New	2,100.00	2,100.00
3	REMOVE & REPLACE BODY KIT	New	80.00	80.00
4	REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	80.00
5	TO TRANSFER REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
6	REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
7	TO APPLY SEALANT ON AFFECTED AREA	New	120.00	80.00
8	PERFORM RUST PREVENTION	New	120.00	40.00
9	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
10	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
11	TO SUPPLY MIVEC EMBLEM	New	30.00	30.00
12	TO SUPPLY C & C EMBLEM	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,140.00</b>	<b>5,305.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >