

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012826/EVY3N2**Date:** 29/04/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00147032101

**Claimant Vehicle  
No :** PZ1308E**Insured  
Vehicle No :** YM7636E

Date of Loss: 16/12/2021

Nature of Claim: TP

Claim  
No: SNM21D207355/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **PZ1308E**

Make &amp; Model: MITSUBISHI BE639JRMHDEA, 3.9 D (M)

Engine No: 4D34K33465

Reg. Date: 10/06/2005 (Man. Year: 2005)

Chassis No: BE639JD00218

Colour: White

Odometer: 869751 km

Engine Capacity: 3908 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 195R15

Rear Tyre Size:

195R15

Front Left Side: Dunlop 4 mm

Rear Left Side:

Dunlop 4 mm

Front Right Side: Dunlop 4 mm

Rear Right Side:

Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,812.00	3,472.00	1,340.00	27.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	1,430.00	1,600.00	52.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>7,842.00</b>	<b>4,902.00</b>	<b>2,940.00</b>	<b>37.49</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	548.94	343.14	205.80	37.49
<b>Nett Amount (\$\$)</b>	<b>8,390.94</b>	<b>5,245.14</b>	<b>3,145.80</b>	<b>37.49</b>

**INSPECTION**

Date of Assignment: 20/12/2021

Date Inspected: 22/12/2021

Inspected At:

Connect3 (mandai Estate) (HQ)  
566 Woodlands Road  
Singapore 728697

Estimated Period of Repair: 5.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 29 Apr 2022)	
Parts:	N/A	mitsubishi BE639JRMHDEA 3.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PZ1308E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH PILLAR PANEL	Dented	2,658.00 F	*2,658.00 F
2	1		*REAR RH PILLAR INNER STRUCTURE	Repair	1,340.00 F	*- F
3	1		*REAR RH GLASS MOULDING	Cut	734.00 F	*734.00 F
4	2		*SEALANT	Necessary	80.00 FS	*80.00 FS
					Total Parts (S\$)	4,812.00 3,472.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO REMOVE & REFIT REAR TRIMS,SEATS,UPHOLSTERY ETC TO ASSIST REPAIR	New	300.00	200.00
2	LABOUR TO REMOVE REAR RH SIDE GLASS,REAR RH GLASS TO ASSIST REPAIR	New	600.00	300.00
3	CHECK WIRING	New	30.00	30.00
4	LABOUR CHARGES	New	900.00	600.00
5	SPRAY PAINTING	New	1,200.00	300.00
<b>Gross Labour Cost (\$)</b>			<b>3,030.00</b>	<b>1,430.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >