

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012836/KQY3N2**Date:** 27/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCNA00182022100

**Claimant Vehicle No :** GBC5517D **Insured Vehicle No :** SMU6931J

Date of Loss: 17/12/2021 Nature of Claim: TP Claim No: SNM21D207373/C02/THAMYL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **GBC5517D**

Make & Model: MERCEDES-BENZ 316CDI/3665, 2.1 (A) Engine No: 65195531279705

Reg. Date: 22/01/2013 (Man. Year: 2013) Chassis No: WDB9066332S718047

Colour: Yellow Odometer: 113571 km

Engine Capacity: 2143 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 235/65 R16 Rear Tyre Size: 235/65 R16

Front Left Side: Continental 7 mm Rear Left Side: Kumho 9 mm

Front Right Side: Continental 7 mm Rear Right Side: Kumho 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,724.00	2,914.00	810.00	21.75
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	3,030.00	2,380.00	650.00	21.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,764.00</b>	<b>5,304.00</b>	<b>1,460.00</b>	<b>21.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,200.00</b>		
<b>(S\$)</b>	6,764.00	4,200.00	2,564.00	37.91
<b>+ GST 7.00/7.00% (S\$)</b>	473.48	294.00	179.48	37.91
<b>Nett Amount (S\$)</b>	<b>7,237.48</b>	<b>4,494.00</b>	<b>2,743.48</b>	<b>37.91</b>

**INSPECTION**

Date of Assignment: 21/12/2021 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 20/12/2021 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
Blk 1019 #01-374/382, Yishun Industrial Park A  
Singapore 768761

Estimated Period of Repair: 6.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 26 Jan 2022)	
<b>Parts:</b>	N/A	MERCEDES-BENZ 316CDI/3665 2.1 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBC5517D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Buckled	395.00 F	*395.00 F
2	1		*1 PC REAR BUMPER RH REFLECTOR	Broken	12.00 F	*12.00 F
3	1		*1 PC REAR BUMPER RH SIDE PAD	Bent	110.00 F	*110.00 F
4	1		*1 PC REAR BUMPER REINFORCEMENT	Repair	460.00 F	*- F
5	1		*2 PCS REAR BUMPER TOP CLIPS @3/PC	Necessary	6.00 F	*6.00 F
6	1		*1 PC REAR BUMPER RH TOP PROTECTOR	Dented	20.00 F	*20.00 F
7	1		*1 PC RH TAILLAMP COVER	Serviceable	185.00 F	*- F
8	1		*1 PC RH TAILLAMP HOUSING	Missing	230.00 F	*230.00 F
9	1		*1 PC RH TAILLAMP SOCKET	Missing	39.00 F	*39.00 F
10	1		*3 PCS RH TAILLAMP CLIPS @3/PC	Missing	9.00 F	*9.00 F
11	1		*1 PC RH TAILGATE	Bent	1,450.00 F	*1,450.00 F
12	1		*1 PC RH TAILGATE LOWER HINGE	Repair	165.00 F	*- F
13	1		*1 PC RH TAILGATE INNER RUBBER	Dented/Distorted	230.00 F	*230.00 F
14	1		*1 PC RH TAILGATE EMBLEM (316 CDI)	Necessary	105.00 F	*105.00 F
15	1		*1 PC LH TAILGATE EMBLEM (SPRINTER)	Necessary	88.00 F	*88.00 F
<b>Supplementary #1</b>						
16	1		*1 PC RH TAILGATE INNER LOCK	Dented	220.00 F	*220.00 F

F=Franchise part.

<b>Total Parts (\$\$)</b>	<b>3,724.00</b>	<b>2,914.00</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	1 PC STICKER - 70KM.H Necessary	10.00	10.00
<b>Sub Total (\$\$)</b>			<b>10.00</b>	<b>10.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMP, BUMPER SIDE PAD, RH TAILGATE, LOCK ASSY, TO CUT, WELD & RENEW RH TAILLAMP PANEL, KNOCK & REPAIR REAR RH SIDE PANEL, LH SIDE PANEL, REAR END PANEL, REAR RH CORNAL FLOOR BOARD AND REALIGN THE SAME	New	1,000.00	800.00
2	PUTTY & RESPRAY ON RH & LH TAILGATE, BOTH SIDE PANELS, TAILLAMP PANEL AND REAR RH CORNAL FLOOR BOARD PANEL & ALL AFFECTED AREAS	New	1,200.00	1,000.00
3	TO REWRITE ADVERTISEMENT	New	800.00	550.00
4	RUSTPROOFING	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,030.00</b>	<b>2,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >