

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21012838/T1QF3N2**Date:** 18/01/2022**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBK2886R**Insured Vehicle No :** SMF8957B

Date of Loss: 14/12/2021

Nature of Claim: TP

Claim No: 4278945777SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBK2886R**

Make & Model: MITSUBISHI L200, 2.4 D DOUBLE CAB (M)

Engine No: 4N15UDJ8040

Reg. Date: 23/03/2020 (Man. Year: 2018)

Chassis No: MMCJJKL20KH007290

Colour: Silver

Odometer: 0 km

Engine Capacity: 2442 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/R16

Rear Tyre Size: 205/R16

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/12/2021

Date Inspected: 22/12/2021 Inspected At:

Boon Kim & Co (HQ)

Blk 15 Defu Lane 10, Defu Indus Park D #01-388

Singapore 539196

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

MARKET VALUE: \$120,000.00 (EST)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Deformed	0.00 F	*- F
3	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
4	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
5	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
6	1		*TAILGATE	Bent	0.00 F	*- F
7	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
8	1		*TAILGATE LOWER PANEL	Repair	0.00 F	*- F
9	1		*TAILGATE LOWER PANEL RUBBER	Cut	0.00 F	*- F
10	1		*REAR LH FENDER	Repair	0.00 F	*- F
11	1		*STICKER 70KM/H	Necessary	0.00 F	*- F
					F=Franchise part.	
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >