

AXA Insurance Pte Ltd
8 Shenton way #24-01 AXA Tower
Singapore 068811



VICOM LTD
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

DAMAGE ASSESSMENT REPORT

www.vicom.com.sg
Company Registration No: 198100320K

GENERAL INFORMATION			
VAC Ref. No.	: 570858	Claim No.	: S1M03MP9
Accident Date	: 21/11/2021	Claim Type	: THIRD PARTY
Assignment Date	: 24/11/2021	Policy No.	:
Survey Date	: 25/11/2021		
Report Date	:	Insured Veh.	: SHA4293U
VEHICLE PARTICULARS			
Vehicle No.	: SMF3084C	Chassis No.	: RU31303486
Registration Date	: 01/11/2018	Engine No.	: LEB6723493
Make	: HONDA	Engine Cap.	: 1496 CC
Model	: VEZEL HYBRID 1.5X AU	Transmission	: AUTO
		Colour	: RED
CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 62501		
TYRES	SIZE	MAKE	BALANCE (mm)
FRONT RH	215/60 R16	YOKOHAMA	7
FRONT LH	215/60 R16	YOKOHAMA	7
REAR RH	215/60 R16	YOKOHAMA	7
REAR LH	215/60 R16	YOKOHAMA	7
SURVEY CONDUCTED AT			
AESOP AUTOMOTIVE CENTRE BLK 5032 AMK IND PARK 2 # 01-299/301 S569535 MR TOH:64812002/ MR ONG:64830007			
REMARKS			
[1]Workshop did not give repair estimate.			
[2]We have not authorised repairs. This survey was carried out on without prejudice basis.			

DAMAGE ASSESSMENT REPORT**Annex A: List of damaged parts**

#	Qty	Vehicle Parts Description	Condition
1	1	Tailgate	Dented
2	1	Tailgate Lock	Bent
3	1	Tailgate Weatherstrip	Deformed
4	1	Rear Bumper	Deformed
5	1	Rear Bumper Lower Garnish	Deformed
6	1	Rear End Panel	Buckled
7	1	Rear End Panel Top Garnish	Deformed
8	1	Toolbox	Deformed
9	1	Floor Panel	Buckled
10	1	Rear Left Under Cover	Deformed

VICOM LTD
DAMAGE ASSESSMENT REPORT
Annex B: Comments

SMF3084C @ 21/11/2021

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained rear portion damage.

The damages seen during our survey were tailgate, tailgate lock, tailgate weather strip, rear bumper, rear bumper lower garnish, rear end panel, rear end panel top garnish, tool box, floor panel, rear left under cover and surrounding areas. A fuller detailed description of the damages is in Annex A of this damage assessment report.

We enclose 54 photographs of this vehicle taken during our attendance.

The repair estimate was not available during our survey attendance.

This Vehicle has :

- a) estimated pre-accident value = S\$82,000.00
- b) estimated salvage value = S\$35,002.00
- c) economical repair value = S\$46,998.00

As this vehicle was more than 3 years old during the accident, we assess repairs on a lumpsum basis is appropriate.

REMARKS

The repair cost is around \$4,200.00 to \$5,000.00 and it take approximately 7 working days to complete.



Favacho Patrick Gerard
for VICOM Ltd