

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG121012845/ATF3N2**Date:** 05/05/2022**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBE2352X**Insured Vehicle No :** GBB7208M

Date of Loss: 18/12/2021

Nature of Claim: TP

Claim No: CDMCG21002440

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBE2352X**

Make & Model: NISSAN NV350, 2.5 5MT 5DR EURO V (A)

Engine No: YD25379883A

Reg. Date: 29/09/2015 (Man. Year: 2015)

Chassis No: JN1MC2E26Z0005049

Colour: Grey

Odometer: 167822 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C

Rear Tyre Size: 195R15C

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,109.04	11,163.83	8,945.21	44.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	2,990.00	530.00	15.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,629.04	14,153.83	9,475.21	40.10
Approved Total (Overridden) (S\$)		11,300.00		
Nett Amount (S\$)	23,629.04	11,300.00	12,329.04	52.18

INSPECTION

Date of Assignment: 20/12/2021

Date Inspected: 20/12/2021 Inspected At:

Ryder Auto Pte Ltd (HQ)

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit

Singapore 417921

Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 May 2022)	
Parts:	N/A	NISSAN NV350 2.5 5MT 5DR EURO V (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE2352X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	796.20 FN	*667.00 FN
2	10		*REAR BUMPER CLIPS	Necessary	30.00 FN	*30.00 FN
3	3		*REAR BUMPER CENTER BRACKET	Not Necessary	80.00 FN	*- FN
4	2		*REAR BUMPER O/S & N/S RETAINER	Necessary	246.20 FN	*68.00 FN
5	1		*REAR TAIL-GATE	Distorted	2,200.40 FN	*1,998.00 FN
6	1		*REAR TAIL-GATE WEATHERSTRIP	Cut	286.10 FN	*286.10 FN
7	1		*REAR TAIL-GATE NISSAN EMBLEM	Necessary	86.70 FN	*86.70 FN
8	1		*REAR TAIL-GATE NV 350 EMBLEM	Necessary	106.70 FN	*106.70 FN
9	1		*REAR TAIL-GATE LOCK (UPPER)	Damaged	268.40 FN	*268.40 FN
10	1		*REAR TAIL-GATE LOCK (LOWER)	Not Necessary	136.10 FN	*- FN
11	1		*REAR LOCK ACTUATOR	Damaged	355.60 FN	*355.60 FN
12	1		*REAR WIPER MOTOR	Not Necessary	310.20 FN	*- FN
13	1		*REAR TAIL-GATE MOULDING (CHROME)	Cracked	586.20 FN	*586.20 FN
14	1		*REAR TAIL-GATE INNER TRIM	Torn	266.10 FN	*168.00 FN
15	2		*REAR TAIL-GATE O/S & N/S SHOCK ABSORBER	Not Necessary	468.00 FN	*- FN
16	2		*REAR TAIL-GATE O/S & N/S HINGES	Not Necessary	368.00 FN	*- FN
17	2		*REAR TAIL-GATE O/S & N/S RUBBER STOPPER	Not Necessary	40.00 FN	*- FN
18	1		*REAR END PANEL OUTER	Dented	584.80 FN	*584.80 FN
19	1		*REAR END PANEL STEP PANEL	Bent	234.60 FN	*234.60 FN
20	1		*REAR END PANEL TOP GARNISH CHROME	Bent	140.00 FN	*140.00 FN
21	2		*REAR O/S & N/S TAIL-LAMP	Cracked	697.20 FN	*697.20 FN
22	2		*REAR O/S & N/S TAIL-LAMP PANEL	Repair	846.40 FN	*- FN
23	1		*REAR O/S BODY PANEL	Repair	1,867.80 FN	*- FN
24	1		*REAR REAR VIEW MOTOR	Not Necessary	250.00 FN	*- FN
25	1		*REAR WINDSCREEN	Shattered	954.60 FN	*954.60 FN
26	2		*REAR REG NO PLATE LAMP	Not Necessary	166.00 FN	*- FN
27	1		*FRONT BUMPER	Deformed	743.60 FN	*743.60 FN
28	2		*FRONT BUMPER O/S & N/S RETAINER	Necessary	232.40 FN	*94.00 FN
29	2		*FRONT BUMPER O/S & N/S FOG LAMP	Not Necessary	540.00 FN	*- FN
30	2		*FRONT BUMPER O/S & N/S FOG LAMP BRACKET	Not Necessary	146.40 FN	*- FN
31	1		*FRONT PANEL	Dented	1,396.40 FN	*1,396.40 FN
32	2		*FRONT O/S & N/S HEADLAMP	Cracked	1,042.60 FN	*1,042.60 FN
33	1		*FRONT GRILLE MIDDLE (CHROME)	Cracked	823.50 FN	*495.00 FN
34	1		*FRONT GRILLE LOWER	Not Necessary	296.50 FN	*- FN
35	2		*REAR BUMPER O/S & N/S CORNER CLIPS	Necessary	40.00 FS	*20.00 FS
36	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
37	1		*REAR TAIL-GATE 70KMPH EMBLEM	Necessary	15.00 FS	*15.00 FS
38	1		*REAR WIPER	Not Necessary	60.00 FS	*- FS
39	6		*REAR TAIL-GATE MOULDING (CHROME) CLIPS	Necessary	12.00 FS	*12.00 FS
40	1		*REAR TAIL-GATE INNER TRIM CLIPS (12 Pcs)	Necessary	36.00 FS	*20.00 FS
41	1		*REAR TAIL-GATE FLOOR PLYWOOD	Not Necessary	450.00 FS	*- FS
42	1		*REAR WINDSCREEN MOULDING	Necessary	80.00 FS	*80.00 FS
43	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
44	1		*REAR REG NO PLATE	Bent	45.00 FS	*30.00 FS
45	6		*FRONT GRILLE MIDDLE CLIPS	Necessary	18.00 FS	*18.00 FS

Report was unsubmitted during this print-out.

5/5/22, 3:52 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	6		*FRONT GRILLE LOWER CLIPS	Not Necessary	18.00 FS	*- FS
47	1		*FRONT REGN NO PLATE	Not Necessary	45.00 FS	*- FS
48	1		*REAR CARPET	Not Necessary	300.00 FN	*- FN
49	1		*REAR BOOT FLOOR PANEL	Repair	1,933.10 FN	*- FN
50	1		*REAR TAILGATE INNER TRIM	Torn	145.60 FN	*145.60 FN
51	1		*REAR LOCK COVER	Not Necessary	58.00 FN	*- FN
52	1		*SPARE WHEEL TYRE BRACKET	Damaged	289.60 FN	*289.60 FN
53	1		*SPARE WHEEL TYRE BRACKET GARNISH	Not Necessary	110.20 FN	*- FN
54	1		*REAR END PANEL INNER	Dented	625.40 FN	*460.00 FN
F=Franchise part. S=SpcNett. N=NettItemDisc.						
Sub Total (S\$)					22,214.60	12,353.70
- Nett Item Discount on N Items 10.00/10.00% (S\$)					2,105.56	1,189.87
Total Parts (S\$)					20,109.04	11,163.83
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE DAMAGED PORTION,STRAIGHTEN & WELDING	New	1,600.00	1,400.00
2	TO SPRAY PAINTING	New	1,400.00	1,200.00
3	TO REMOVE & REPLACE REAR WINDSCREEN	New	160.00	120.00
4	TO REMOVE & REPLACE REAR REVERSE SENSOR	New	80.00	50.00
5	TO REMOVE AND REPLACE REAR TAIL-GATE FITTINGS	New	120.00	80.00
6	TO CHECK WIRING	New	80.00	60.00
7	TO RE-SEAL ANTI-RUST	New	80.00	80.00
Gross Labour Cost (\$\$)			3,520.00	2,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >