

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG21012848/TGA3Q2**Date:** 27/07/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SHA9430H**Insured Vehicle No :** SLL2661Z

Date of Loss: 09/12/2021

Nature of Claim: TP

Claim No: 9820558639SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHA9430H**

Make &amp; Model: HYUNDAI AE IONIQ, 1.6 (A)

Engine No: G4LEKU297756

Reg. Date: 02/07/2019 (Man. Year: 2019)

Chassis No: KMHC851CVKU164618

Colour: Yellow

Odometer: 239779 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 6 mm

Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm

Rear Right Side: West Lake 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 5,724.72          | 4,527.68          | 1,197.04          | 20.91         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 2,020.00          | 1,550.00          | 470.00            | 23.27         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Gross Total (S\$)</b>                         | <b>7,744.72</b>   | <b>6,077.68</b>   | <b>1,667.04</b>   | <b>21.52</b>  |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 542.13            | 425.44            | 116.69            | 21.52         |
| <b>Nett Amount (S\$)</b>                         | <b>8,286.85</b>   | <b>6,503.12</b>   | <b>1,783.73</b>   | <b>21.52</b>  |
| <b>+ Loss of Use (14.0 x S\$50.00/day) (S\$)</b> |                   | 700.00            |                   |               |
| <b>+ Car Rental (14.0 x S\$125.19/day) (S\$)</b> |                   | 1,752.66          |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                    |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>8,957.78</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>               |                   | <b>8,950.00</b>   |                   |               |

INSPECTION

Date of Assignment: 20/12/2021

Date Inspected: 20/12/2021 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition                    | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------|------------------------------|-------------|--------------|
| 1   | 1   |          | *C                                   | Necessary                    | 459.40 FL   | *459.40 FL   |
| 2   | 1   |          | *REAR BUMPER CENTRE MOULDING         | Distorted                    | 451.25 FL   | *451.25 FL   |
| 3   | 1   |          | *REAR BUMPER REINFORCEMENT           | Cracked                      | 394.80 FL   | *394.80 FL   |
| 4   | 1   |          | *REAR BUMPER STAY LH/RH              | N/S Not Necessary / O/S Bent | 276.20 FL   | *138.10 FL   |
| 5   | 1   |          | *REAR BUMPER LOWER CENTRE MOULDING   | Missing                      | 155.00 FL   | *155.00 FL   |
| 6   | 1   |          | *REAR CENTRE UNDER COVER             | Missing                      | 225.00 FL   | *225.00 FL   |
| 7   | 10  |          | *REAR BUMPER CLIPS                   | Necessary                    | 22.00 FL    | *22.00 FL    |
| 8   | 1   |          | *BOOTLID COVER                       | Bent                         | 2,480.40 FL | *2,480.40 FL |
| 9   | 1   |          | *BOOTLID LOCK UPPER                  | Not Necessary                | 224.00 FL   | *- FL        |
| 10  | 1   |          | *BOOTLID H EMBLEM                    | Not Necessary                | 38.00 FL    | *- FL        |
| 11  | 1   |          | *BOOTLID EMBLEM IONID                | Necessary                    | 31.80 FL    | *31.80 FL    |
| 12  | 1   |          | *BOOTLID EMBLEM HYBRID               | Necessary                    | 24.30 FL    | *24.30 FL    |
| 13  | 1   |          | *REAR END PANEL                      | Bent                         | 532.00 FL   | *532.00 FL   |
| 14  | 1   |          | *REAR PANEL GARNISH                  | Not Necessary                | 346.80 FL   | *- FL        |
| 15  | 1   |          | *BUMPER FOG LAMP                     | Cracked                      | 201.00 FL   | *201.00 FL   |
| 16  | 2   |          | *BUMPER NUMBER PLATE LH/RH           | Distorted                    | 170.60 FL   | *85.30 FL    |
| 17  | 1   |          | *BUMPER HOOK COVER                   | Repair                       | 94.60 FL    | *- FL        |
| 18  | 2   |          | *REAR REFLECTOR LH/RH                | Not Necessary                | 82.90 FL    | *- FL        |
| 19  | 1   |          | *REAR ANTENNA -SMART KEY             | Cracked                      | 40.50 FL    | *40.50 FL    |
| 20  | 2   |          | *REAR BUMPER BRACKET LH/RH           | Not Necessary                | 111.60 FL   | *- FL        |
| 21  | 1   |          | *BOOTLID ADVERTISEMENT               | Not Necessary                | 100.00 FS   | *- FS        |
| 22  | 2   |          | *REAR FENDER ADVERTISEMENT LH/RH     | Not Necessary                | 200.00 FS   | *- FS        |
| 23  | 1   |          | *BOOTLID COMFORT APP STICKER         | Necessary                    | 40.00 FS    | *40.00 FS    |
| 24  | 2   |          | *BOOTLID COMFORT /TEL NUMBER STICKER | Necessary                    | 60.00 FS    | *60.00 FS    |
| 25  | 1   |          | *REAR NUMBER PLATE W/HOLDER          | Cracked                      | 55.00 FS    | *55.00 FS    |
| 26  | 1   |          | *REAR REVERSE SENSOR                 | Not Working                  | 180.00 FS   | *180.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                          |                 |                 |
|----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$)</b>                                    | <b>6,997.15</b> | <b>5,575.85</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$)</b> | 1,272.43        | 1,048.17        |
| <b>Total Parts (\$)</b>                                  | <b>5,724.72</b> | <b>4,527.68</b> |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                              | Particulars                               | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                           |          |                 |                 |
| 1                               | PANEL BEATING                             | New      | 900.00          | 700.00          |
| 2                               | SPRAY PAINTING CHARGE                     | New      | 700.00          | 700.00          |
| 3                               | REMOVE/REFIX REAR WSCREEN AND LOWER GLASS | New      | 180.00          | 0.00            |
| 4                               | CHECK WIRING AND LIGHTING                 | New      | 60.00           | 30.00           |
| 5                               | TUFF KOTE                                 | New      | 60.00           | 30.00           |
| 6                               | REMOVE/REFIX REVERSE SENSOR               | New      | 60.00           | 30.00           |
| 7                               | TOWING FEE                                | New      | 60.00           | 60.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                           |          | <b>2,020.00</b> | <b>1,550.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >