

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS21012881/UTF3N2**Date:** 07/01/2022REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	MPC21P00218600
Claimant Vehicle No :	SLV5934P	Insured Vehicle No :	SNC3262J
Date of Loss:	17/12/2021	Nature of Claim:	TP
		Claim No:	DMPC2100455H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV5934P	Engine No:	L15B4430823
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11230818
Reg. Date:	05/01/2018 (Man. Year: 2017)	Odometer:	80500 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sumitomo 6 mm	Rear Left Side:	Sumitomo 6 mm
Front Right Side:	Sumitomo 6 mm	Rear Right Side:	Sumitomo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,184.60	4,281.60	6,903.00	61.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,350.00	720.00	34.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,254.60	5,631.60	7,623.00	57.51
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	13,254.60	4,500.00	8,754.60	66.05
+ GST 7.00/7.00% (S\$)	927.82	315.00	612.82	66.05
Nett Amount (S\$)	14,182.42	4,815.00	9,367.42	66.05

INSPECTION

Date of Assignment:	20/12/2021	
Date Inspected:	20/12/2021	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jan 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV5934P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	985.20 F	*- FL
2	1		*FRONT BUMPER LOWER	Grazed	650.00 F	*482.00 FL
3	1		*FRONT BUMPER SIDE RETAINER N/S	Bent	66.50 F	*66.50 FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
5	1		*HEADLAMP N/S	Holder Cracked	1,959.20 F	*1,859.10 FL
6	1		*FRONT FENDER N/S	Dented	788.10 F	*481.20 FL
7	1		*FRONT FENDER OUTER PROTECTOR N/S	Torn	388.50 F	*195.40 FL
8	1		*FRONT FENDER INNER SHIELD N/S	Torn	315.10 F	*185.30 FL
9	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Necessary	50.00 F	*50.00 FL
10	1		*FRONT DOOR N/S	Repair	1,109.20 F	*- FL
11	1		*FRONT SHOCK ABSORBER N/S	Serviceable	655.10 F	*- FL
12	1		*FRONT KNUCKLE ARM N/S	Warped	599.20 F	*482.30 FL
13	1		*FRONT KNUCKLE ARM BEARING N/S	Necessary	350.00 F	*265.00 FL
14	1		*FRONT LOWER ARM N/S	Bent	588.20 F	*485.20 FL
15	1		*FRONT DRIVE SHAFT N/S	Not Necessary	1,280.30 F	*- FL
16	1		*FRONT TYRE N/S	Serviceable	250.00 F	*- FL
17	1		*FRONT SPORT RIM N/S	Warped	1,100.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,184.60	5,202.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	920.40
Total Parts (\$\$)	11,184.60	4,281.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	80.00	30.00
3	TO CONDUCT WHEEL ALIGNMENT	New	120.00	80.00
4	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	New	200.00	120.00
5	TO RESET & REPROGRAMME SYSTEM	New	120.00	0.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	500.00
7	TO PUTTY & SPRAY PAINTING	New	900.00	600.00
Gross Labour Cost (\$\$)			2,070.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >