

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/ICS21012884/ETF3E2

**Date:** 06/07/2022

### REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC20P00215500  
**Claimant Vehicle No :** SMK5332Y **Insured Vehicle No :** SMX931H  
Date of Loss: 18/12/2021 Nature of Claim: TP Claim No: DMPC2100456H/02/JT

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMK5332Y**  
Make & Model: HYUNDAI OS KONA, EV (A) Engine No: HIDDEN  
Reg. Date: 15/04/2019 (Man. Year: 2019) Chassis No: KMHK281GUKU024579  
Colour: Grey Odometer: 169213 km  
Engine Capacity: 0 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17  
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm  
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,573.54	5,446.06	4,127.48	43.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,540.00	2,730.00	1,810.00	39.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,113.54</b>	<b>8,176.06</b>	<b>5,937.48</b>	<b>42.07</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,550.00</b>		
<b>(S\$)</b>	14,113.54	6,550.00	7,563.54	53.59
<b>+ GST 7.00/7.00% (S\$)</b>	987.95	458.50	529.45	53.59
<b>Nett Amount (S\$)</b>	<b>15,101.49</b>	<b>7,008.50</b>	<b>8,092.99</b>	<b>53.59</b>

### INSPECTION

Date of Assignment: 20/12/2021  
Date Inspected: 21/12/2021 Inspected At: Pegasus Engineering & Trading Pte Ltd (Kian Teck)  
74 Kian Teck Road  
Singapore 628800  
Estimated Period of Repair: 10.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Jul 2022)
<b>Parts:</b>	143	HYUNDAI OS KONA EV (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMK5332Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	495.65 FL	*495.65 FL
2	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE RETAINER	Broken	170.50 FL	*170.50 FL
4	1		*REAR BUMPER TOW COVER	Broken	25.20 FL	*25.20 FL
5	1		*REAR BUMPER UPPER CENTER GARNISH (FOLLOW VEHICLE COLOUR)	Broken	296.35 FL	*296.35 FL
6	1		*REAR BUMPER LOWER CENTER GARNISH 9SILVER COLOUR)	Broken	126.95 FL	*126.95 FL
7	1		*REAR BUMPER REVERSE SENSOR (4PCS)	Shorted (2Pcs Only)	757.60 FL	*378.80 FL
8	1		*REAR BUMPER UNDER LOWER CENTRE COVER (BLACK COLOUR)	Broken	295.80 FL	*295.80 FL
9	1		*REAR BUMPER SIGNAL LAMP	O/S Cut	514.20 FL	*257.10 FL
10	1		*REAR ANTENNA SMART KEYLESS	Shorted	128.20 FL	*128.20 FL
11	1		*REAR REINFORCEMENT	Dented	335.80 FL	*335.80 FL
12	1		*REAR REINFORCEMENT ARM (2PCS)	Bent(1Pc Only)	316.00 FL	*158.00 FL
13	2		*REAR REINFORCEMENT UPPER BRACKET	Crushed	76.00 FL	*76.00 FL
14	3		*REAR REINFORCEMENT LOWER BRACKET	Crushed	84.00 FL	*84.00 FL
15	1		*REAR BLIND SPORT SENSOR	Shorted	980.57 FL	*980.57 FL
16	1		*REAR END PANEL	Dented	785.65 FL	*785.65 FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	235.20 FL	*- FL
18	1		*REAR SPARE TYRE PANEL	Repair	885.90 FL	*- FL
19	1		*REAR SPARE TYRE PANEL FLOOR BOARD	Not Necessary	278.50 FL	*- FL
20	1		*REAR TAILGATE	Dented	1,928.95 FL	*1,540.00 FL
21	2		*REAR TAILGATE HINGE	Not Necessary	311.20 FL	*- FL
22	2		*REAR TAILGATE ABSORBER	Not Necessary	397.00 FL	*- FL
23	1		*REAR TAILGATE OUTER MOULDING	Not Necessary	245.20 FL	*- FL
24	1		*REAR TAILGATE HYUNDAI EMBLEM	Necessary	55.00 FL	*55.00 FL
25	1		*REAR TAILGATE KONA BADGE	Necessary	45.00 FL	*45.00 FL
26	1		*REAR TAILGATE ELECTRIC BADGE	Necessary	45.00 FL	*45.00 FL
27	2		*REAR TAILGATE REFLECTOR	Not Necessary	807.00 FL	*- FL
28	1		*REAR TAILGATE TRIM BOARD	Not Necessary	228.80 FL	*- FL
29	10		*REAR TAILGATE TRIM BOARD CLIPS	Not Necessary	50.00 FL	*- FL
30	1		*REAR TAILGATE LOCK	Not Necessary	213.70 FL	*- FL
31	2		*REAR TAILGATE NO PLATE LAMP	Not Necessary	170.00 FL	*- FL
32	1		*REAR TAILGATE STRIKER (CATCH)	Not Necessary	89.00 FL	*- FL
33	1		*REAR WINDSCREEN MOULDING	Necessary	198.00 FL	*198.00 FL
34	1		*REAR WEATHERSTRIP	Torn	200.00 FL	*200.00 FL
35	2		*REAR FENDER (NPA)	Repair	0.00 FL	*- FL
36	1		*REAR NO PLATE & CASING	Cut	60.00 FS	*40.00 FS
37	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,936.92</b>	<b>6,787.57</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,363.38	1,341.51



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING FEE	New	100.00	60.00
2	TO REMOVE AND REPLACE REAR BUMPER REVERSE SENSOR	New	100.00	30.00
3	TO REMOVE & TRANSFER REAR WINDSCREEN GLASS TO THE NEW TAILGATE	New	200.00	50.00
4	TO REMOVE AND REFIT REAR INTERIOR FITTINGS, TRIMMINGS, GARNISH FLOOR CARPET TO ENABLE REPAIR	New	120.00	50.00
5	TO REMOVE & REARRANGE ELECTRICAL WIRING SYSTEM FOR FACILITATE REPAIR	New	100.00	30.00
6	TO DISCONNECT & CONNECT BACK ELECTRICAL POWER	New	200.00	80.00
7	TO APPLY RUSTPROOFING / TUFFCOATING TREATMENT TO REPLACED PARTS	New	120.00	30.00
8	TO REMOVE, REPLACED DAMAGED BODYPARTS, REPAIR & REALIGN BODYWORK & WHERE CONSISTANT TO THE ACCIDENTS	New	2,000.00	1,400.00
9	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS	New	1,600.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,540.00</b>	<b>2,730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >