

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012888/R1VY3N2**Date:** 25/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00021322100

Claimant Vehicle No : SNC5490D **Insured Vehicle No :** GBE7418H

Date of Loss: 16/12/2021 Nature of Claim: TP Claim No: SNM21D207377/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNC5490D**

Make & Model: VOLKSWAGEN T CROSS R-LINE, 999cc (A) Engine No: DKJ113832

Reg. Date: 28/10/2021 (Man. Year: 2021) Chassis No: WVGZZC1ZNY000798

Colour: White Odometer: 1603 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R17 Rear Tyre Size: 205/55R17

Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,593.40	4,340.24	2,253.16	34.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,720.00	7,740.00	6,980.00	47.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,313.40	12,080.24	9,233.16	43.32
+ GST 7.00/7.00% (S\$)	1,491.94	845.62	646.32	43.32
Nett Amount (S\$)	22,805.34	12,925.86	9,879.48	43.32

INSPECTION

Date of Assignment: 20/12/2021

Date Inspected: 23/12/2021 Inspected At: Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Jan 2022)
Parts:	M1-SUV	VOLKSWAGEN T CROSS R-LINE 999cc (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC5490D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID	Bent	2,521.19 FS	*2,521.19 FS
2	2		*1K WINDOW ADHESIVE	Necessary	102.60 FS	*102.60 FS
3	1		*ALL PURPOSE CLEANER	Necessary	97.65 FS	*97.65 FS
4	1		*PRIMER	Necessary	28.52 FS	*28.52 FS
5	1		*ACTIVATOR FOR PRECOATED W	Necessary	26.23 FS	*26.23 FS
6	2		*APPLICATOR	Necessary	20.94 FS	*20.94 FS
7	8		*GROMMET	Necessary	13.60 FS	*13.60 FS
8	6		*RIVETTED CAP NUT	Necessary	15.00 FS	*15.00 FS
9	1		*PACKING ADHESIVE REAR NUMBER PLATE PACKING	Necessary	30.60 FS	*30.60 FS
10	2		*EXPANDING NUT	Necessary	3.86 FS	*3.86 FS
11	1		*SCHRIFTZUG CHROM NAME PLATE-T-CROSS	Necessary	66.37 FS	*66.37 FS
12	1		*COVER FOR BUMPER PRIMED REAR BUMPER (UPPER)	Not Necessary	1,084.17 FS	*- FS
13	1		*SPOILER PRIMED REAR BUMPER (CTR)	Scratched	242.46 FS	*242.46 FS
14	1		*REAR DIFFUSOR SATIN BLACK REAR BUMPER (LOWER BLACK)	Deformed	190.49 FS	*190.49 FS
15	1		*BUMPER BRACKET REINFORCEMENT	Not Necessary	564.88 FS	*- FS
16	1		*SCHAUM-FULLSTUCK BUMPER FOAM	Not Necessary	93.44 FS	*- FS
17	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Not Necessary	67.23 FS	*- FS
18	1		*FUHRUNGSPROFIL LHR BUMPER BRACKET (UPPER)	Not Necessary	36.31 FS	*- FS
19	1		*FUHRUNGSPROFIL RHR BUMPER BRACKET (UPPER)	Not Necessary	36.31 FS	*- FS
20	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	36.31 FS	*- FS
21	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	36.31 FS	*- FS
22	2		*EXPANDING NUT	Not Necessary	3.68 FS	*- FS
23	2		*SENSOR BRACKET	Not Necessary	23.06 FS	*- FS
24	1		*SENSOR BRACKET	Not Necessary	11.53 FS	*- FS
25	1		*SENSOR BRACKET	Not Necessary	11.53 FS	*- FS
26	1		*SENSOR BRACKET PRIMED	Not Necessary	13.15 FS	*- FS
27	1		*SENSOR BRACKET PRIMED	Not Necessary	13.15 FS	*- FS
28	1		*2K-PLASTIC ADHESIVE	Not Necessary	81.39 FS	*- FS
29	1		*BONDING AGENT FOR PLASTIC	Not Necessary	65.42 FS	*- FS
30	1		*REFLECTOR LH	Not Necessary	75.29 FS	*- FS

Report was unsubmitted during this print-out.

1/25/22, 12:08 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	1		*FRT NUMBER PLATE	Necessary	80.00 FS	*80.00 FS
32	1		*REAR NUMBER PLATE	Necessary	80.00 FS	*80.00 FS
33	1		*REINFORCEMENT	Bent	636.29 FS	*636.29 FS
34	1		*SCHAUM-FULLSTUCK	Bent	93.91 FS	*93.91 FS
35	1		*REFLECTOR	Cracked	78.92 FS	*78.92 FS
36	3		*BOLT HEX,HD	Necessary	11.61 FS	*11.61 FS
F=Franchise part. S=SpcNett.						
				Total Parts (\$\$)	6,593.40	4,340.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LTA BREAKSEAL (OPC PLATE)	New	650.00	650.00
4	LABOUR FRT	New	1,680.00	840.00
5	SPRAY PAINT FRT	New	1,600.00	0.00
6	LABOUR REAR	New	4,200.00	1,680.00
7	SPRAY PAINT REAR	New	4,000.00	2,400.00
8	R&R REAR W/SCREEN	New	840.00	840.00
9	TRANSFER BOOT LID MECHANISM	New	840.00	420.00
10	REAR WATER LEAK TEST	New	150.00	150.00
Gross Labour Cost (\$\$)			14,720.00	7,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >