



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205535

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 08/09/2022
Reference CC6/CTI21012889/Aea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SJB 9330J
Insured Veh. SGW 1383J
Claim No. SNM21D207394/C02
Policy No. DMPCSNW00246322100
Accident Date 18/12/2021
Inspection Date 20/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC6/CTI21012889/Aea3q2	
			Date: 08/09/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGW 1383J	Veh. Inspected	SJB 9330J	
Policy No.	DMPCSNW00246322100	Coverage (\$)	0.00	
Claim No.	SNM21D207394/C02	Excess (\$)	0.00	
Assign From		Assign Date	20/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU11210731	Colour	SILVER	
Odometer	139792 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/12/2021	Inspection Date	20/12/2021	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 9330J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	840.00	745.00
2	REAR BUMPER O/S & N/S TOP GARNISH	N/S DEFORMED	586.40	195.00
2	REAR BUMPER O/S & N/S REFLECTOR	NOT NECESSARY	208.00	-
2	REAR BUMPER O/S & N/S RETAINER	NECESSARY	125.00	125.00
1	REAR END PANEL	DISTORTED	611.90	611.90
1	REAR END PANEL INNER TRIM	DEFORMED	150.00	150.00
1	REAR BUZZER	CRACKED	85.00	85.00
1	REAR O/S TAIL LAMP PANEL	TO REPAIR SEE LABOUR	213.00	-
2	REAR O/S & N/S TAIL LAMP	CUT	940.00	940.00
1	REAR TAIL GATE	DISTORTED	1,178.00	1,100.00
1	REAR O/S & N/S TAIL GATE STOPPER	NOT NECESSARY	80.00	-
1	REAR TAIL GATE WEATHERSTRIP	CUT	265.00	265.00
1	REAR TAIL GATE 'HONDA' EMBLEM	NOT NECESSARY	55.00	-
1	REAR TAIL GATE 'VEZEL' EMBLEM	NECESSARY	55.00	55.00
1	REAR TAIL GATE INNER TRIM	CRACKED	310.00	310.00
2	REAR O/S & N/S TAIL GATE INNER TRIM	NOT NECESSARY	87.00	-
1	REAR TAIL GATE HANDLE (INNER)	NOT NECESSARY	80.00	-
1	REAR TAIL GATE LOCK (UPPER)	DAMAGED	260.60	260.60
2	REAR TAIL GATE O/S & N/S REFLECTOR	N/S CRACKED / O/S CUT	845.60	845.60
1	REAR SPARE WHEEL TANK UNDERCOVER (ADDITIONAL)	DEFORMED	310.60	310.60
1	REAR SPARE WHEEL TANK PANEL (ADDITIONAL)	TO REPAIR SEE LABOUR	998.70	-
1	REAR SPARE WHEEL TANK TOOLBOX (ADDITIONAL)	CRACKED	245.60	245.60
1	REAR SPARE WHEEL BOARD COVER (ADDITIONAL)	CRACKED	261.10	261.10
2	REAR SPARE WHEEL BOARD COVER O/S & N/S CHROME GARNISH	N/S CRACKED	165.40	82.70
2	REAR N/S & O/S WHEEL ARCH	N/S DEFORMED	242.00	121.00
2	REAR N/S & O/S FENDER INNER TRIM	N/SCRACKED	615.60	285.00
	LESS 20% DISCOUNT		-1,962.90	-1,398.82
			7,851.60	5,595.28

Report Ref No. CC6/CTI21012889/Aea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
10	REAR BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
2	REAR BUMPER SCREW CLIPS (SN)	NOT NECESSARY	20.00	-
2	REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
2	REAR O/S & N/S TAIL LAMP CLIPS (SN)	NECESSARY	20.00	20.00
12	REAR TAIL GATE INNER TRIM CLIPS (SN)	NECESSARY	34.00	34.00
12	REAR O/S & N/S TAIL GATE INNER TRIM CLIPS (SN)	NOT NECESSARY	34.00	-
4	REAR WINDSCREEN MOULDING (SN)	NECESSARY	145.00	145.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR REGN NO PLATE (SN)	DEFORMED	45.00	30.00
1	REAR REGN NO PLATE BRACKET (SN)	DEFORMED	29.00	29.00
12	REAR O/S & N/S FENDER INNER TRIM CLIPS (SN)	NECESSARY	34.00	30.00
			741.00	578.00
	<u>LABOUR</u>			
	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING.INCLUSIVE OF THE REPAIR OF REAR O/S TAIL LAMP PANEL AND REAR SPARE WHEEL TANK PANEL .		1,200.00	1,000.00
	TO SPRAY PAINTING.		900.00	800.00
	TO CHECK WIRING .		200.00	30.00
	TO RE-SET ELECTRIAL SYSTEM & CHECK FOR FAULT CODE.	NOT NECESSARY	180.00	-
	TO REMOVE AND REFIT REAR WINDSCREEN .		150.00	120.00
	TO REMOVE & REPLACE REAR REVERSE SENSOR.		50.00	50.00
	TO CHECK WIRING .		60.00	30.00
	TO RESEAL ANTI RUST.		50.00	50.00
			2,790.00	2,080.00
GRAND TOTAL			11,382.60	8,253.28

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,600.00
---	--	--	-----------------

Report Ref No. CC6/CTI21012889/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJB 9330J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJB 9330J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

