

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21012910/AGA3Q2**Date:** 14/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993703
<b>Claimant Vehicle No :</b>	SMY8003D	<b>Insured Vehicle No :</b>	GBG6263H
Date of Loss:	19/12/2021	Nature of Claim:	TP
		Claim No:	1150654055SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMY8003D</b>	Engine No:	A25A0A01464
Make & Model:	TOYOTA CAMRY, 2.5 HYBRID CVT (A)	Chassis No:	JTNB23HK203075013
Reg. Date:	25/03/2021 (Man. Year: 2020)	Odometer:	28090 km
Colour:	Silver		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,141.30	866.25	2,275.05	72.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	530.00	590.00	52.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,261.30</b>	<b>1,396.25</b>	<b>2,865.05</b>	<b>67.23</b>
<b>+ GST 7.00/7.00% (S\$)</b>	298.29	97.74	200.55	67.23
<b>Nett Amount (S\$)</b>	<b>4,559.59</b>	<b>1,493.99</b>	<b>3,065.60</b>	<b>67.23</b>
<b>+ Loss of Use (2.0 x S\$80.00/day) (S\$)</b>		160.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>Nett Liability (S\$)</b>		<b>1,690.44</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,650.00</b>		

INSPECTION

Date of Assignment:	20/12/2021	
Date Inspected:	20/12/2021	Inspected At: Ryder Auto Pte Ltd (HQ) 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit Singapore 417921
Estimated Period of Repair:	2.0 days	

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,132.40 FL	*656.00 FL
2	2		*REAR BUMPER O/S & N/S LOWER GARNISH (BLACK)	Not Necessary	385.60 FL	*- FL
3	10		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
4	1		*REAR BUMPER ENFORCEMENT	Dented	752.60 FL	*459.00 FL
5	2		*REAR BUMPER O/S & N/S STAY ENFORCEMENT	Not Necessary	330.60 FL	*- FL
6	2		*REAR BUMPER O/S & N/S REFLECTOR	Not Necessary	155.40 FL	*- FL
7	2		*REAR BUMPER O/S & N/S RETAINER	Not Necessary	162.70 FL	*- FL
8	2		*REAR REVERSE SENSOR	Not Necessary	841.20 FL	*- FL
9	1		*REAR BUZZER	Not Necessary	387.90 FL	*- FL
					<b>Sub Total (\$)</b>	<b>4,178.40 1,145.00</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	<b>1,037.10 278.75</b>
					<b>Total Parts (\$)</b>	<b>3,141.30 866.25</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	500.00	250.00
2	TO SPRAY PAINTING	New	400.00	250.00
3	TO RE-SEAL ELECTRICAL SYSTEM	New	120.00	0.00
4	TO CHECK WIRING	New	50.00	30.00
5	TO RE-SEAL ANTI-RUST	New	50.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>1,120.00</b>	<b>530.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >