



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2206992

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 10/11/2022
Reference CC6/CTI21012911/Dea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHD 3519K
Insured Veh. GY 353S
Claim No. SNM21D207440/C02
Policy No. DMCVSNW0013442105
Accident Date 19/12/2021
Inspection Date 22/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21012911/Dea3q2	
			Date: 10/11/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 353S	Veh. Inspected	SHD 3519K	
Policy No.	DMCVSNW0013442105	Coverage (\$)	0.00	
Claim No.	SNM21D207440/C02	Excess (\$)	0.00	
Assign From		Assign Date	22/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMGU093414	Colour	BLUE	
Odometer	474297 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/12/2021	Inspection Date	22/12/2021	
Survey held at	Blk 9 Sector C #01-42, Sin Ming Industrial Estate			
Repairer	BIFROST AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3519K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BENT / DENTED	1,106.00	553.00
1	REAR BUMPER BRACKET	NOT NECESSARY	35.60	-
1	REAR FENDER (LH)	DENTED	2,171.40	2,171.40
1	REAR WINDSCREEN MOULDING	NECESSARY	51.80	51.80
1	REAR DOOR (LH)	DENTED	2,201.10	2,201.10
1	REAR DOOR RUBBER (LH)	NECESSARY	280.50	280.50
1	REAR DOOR REGULATOR (LH)	NOT NECESSARY	660.90	-
1	REAR DOOR POWER WINDOW MOTOR	NOT NECESSARY	386.20	-
1	REAR DOOR LOCK ASSY	NOT NECESSARY	468.20	-
1	REAR DOOR TRIM BOARD (LH)	NOT NECESSARY	808.70	-
1	REAR DOOR OUTER HANDLE (LH)	NOT NECESSARY	134.50	-
1	ROCKER PANEL OUTER GARNISH (LH)	TO REPAIR SEE LABOUR	732.80	-
1	ROCKER PANEL OUTER GARNISH CLIP (LH)	NOT NECESSARY	65.00	-
1	REAR TRYE RIM (LH)	DISTORTED	650.60	325.30
1	REAR TYRE WHEEL CAP	CUT	214.20	107.10
1	REAR WHEEL BEARING ING & HUB	DAMAGED	724.00	362.00
1	REAR TRAILING ARM (LH)	DISTORTED	384.00	192.00
1	REAR ASSIST (LH)	DISTORTED	219.40	145.70
1	REAR SHOCK ABSORBER (LH)	DISTORTED	683.70	342.20
1	REAR SHOCK ABSORBER MOUNTING (LH)	NOT NECESSARY	162.60	-
1	REAR CROSS MEMBER	DENTED	2,021.50	2,021.50
1	STABILIZER BAR	NOT NECESSARY	199.60	-
1	STABILIZER LINK	NOT NECESSARY	85.90	-
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	BENT	353.80	353.80
1	REAR KNUCKLE ARM (LH)	DISTORTED	545.60	545.60
1	FRONT FENDER (LH)	DENTED	663.00	663.00
1	FRONT FENDER SHIELD (LH)	NOT NECESSARY	174.90	-
1	FRONT DOOR MIRROR SIDE GARNISH	NOT NECESSARY	225.00	-
1	FRONT DOOR MIRROR ASSY (LH)	NOT NECESSARY	893.50	-

Report Ref No. CC6/CTI21012911/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR (LH)	DENTED	2,256.40	2,256.40
1	FRONT DOOR RUBBER	NECESSARY	290.50	290.50
1	FRONT DOOR GEAR / REGULATOR (LH)	NOT NECESSARY	776.80	-
1	FRONT DOOR POWER MOTOR (RH)	NOT NECESSARY	296.40	-
1	FRONT DOOR TRIM BOARD (LH)	NOT NECESSARY	997.40	-
1	FRONT DOOR INNER LOCK (LH)	NOT NECESSARY	490.80	-
1	FRONT DOOR OUTER HANDLE (LH)	NOT NECESSARY	132.30	-
1	FRONT WHEEL RIM (LH)	NOT NECESSARY	650.60	-
1	FRONT WHEEL HUB CAP (LH)	NOT NECESSARY	214.20	-
1	KNUCKLE ARM (LH)	NOT NECESSARY	1,104.00	-
1	FRONT WHEEL BEARING AND HUB (LH)	NOT NECESSARY	863.80	-
1	FRONT SUSPENSION LOWER ARM (LH)	NOT NECESSARY	595.90	-
1	DOOR CENTRE PILLAR OUTER (LH) (ADDITIONAL)	DENTED	2,527.80	2,527.80
	LESS 20% DISCOUNT		-5,767.33	-3,145.29
			23,069.32	12,581.16
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR DOOR TEL NO. STICKER (SN)	NECESSARY	10.00	10.00
1	REAR DOOR COMFORTDELGRO & APPS STICKER (LH) (SN)	NECESSARY	80.00	80.00
1	REAR TYRE (LH) (SN)	NOT NECESSARY	216.00	-
1	FRONT DOOR COMFORT LOGO (LH) (SN)	NECESSARY	75.00	75.00
1	FRONT TYRE (LH) (SN)	NOT NECESSARY	216.00	-
			643.00	211.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF ROCKER PANEL OUTER GARNISH (LH).		1,800.00	800.00
	SPRAY PAINTING CHARGE.		1,800.00	1,000.00
	WIRING CHARGE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		100.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		150.00	80.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.		120.00	80.00

Report Ref No. CC6/CTI21012911/Dea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIX REVERSE SENSOR.		120.00	40.00
	REMOVE / REFIX UNDERCARRIAGE (RR).		400.00	150.00
	RE-SET REAR ABS SYSTEM.	NOT NECESSARY	400.00	-
	REMOVE / REFIX FUEL TANK.	NOT NECESSARY	150.00	-
	REMOVE / REFIX EXHAUST PIPE.	NOT NECESSARY	150.00	-
	TRANSFER OF DOOR MECHANISM FRONT.		80.00	60.00
	RE-SET FRT POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	TRANSFER OF DOOR MECHANISM REAR.		80.00	60.00
	RE-SET REAR POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.		550.00	150.00
			6,600.00	2,520.00
GRAND TOTAL			30,312.32	15,312.16

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			12,000.00
---	--	--	------------------

Report Ref No. CC6/CTI21012911/Dea3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3519K

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3519K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 3519K

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

