

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012913/TPA3Q2**Date:** 01/11/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800009161
Claimant Vehicle No :	XD3892S	Insured Vehicle No :	SLW1241B
Date of Loss:	15/12/2021	Nature of Claim:	TP
		Claim No:	6249014515SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XD3892S	Engine No:	6398792
Make & Model:	SCANIA R420CA6X4MNZ, 11.7 D (M)	Chassis No:	XLER6X40085215337
Reg. Date:	01/04/2010 (Man. Year: 2009)	Odometer:	13602 km
Colour:	Yellow		
Engine Capacity:	11705 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	13/ R22.5	Rear Tyre Size:	13/ R22.5 (D)
Front Left Side:	Amberstone 8 mm	Rear Left Side:	Amberstone 8/8 mm
Front Right Side:	Amberstone 8 mm	Rear Right Side:	Amberstone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,485.03	6,136.42	348.61	5.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,580.00	980.00	600.00	37.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,065.03	7,116.42	948.61	11.76
Approved Total (Overridden) (S\$)		5,650.00		
(S\$)	8,065.03	5,650.00	2,415.03	29.94
+ GST 7.00/7.00% (S\$)	564.55	395.50	169.05	29.94
Nett Amount (S\$)	8,629.58	6,045.50	2,584.08	29.94
+ Loss of Use (4.0 x S\$150.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,647.50		

INSPECTION

Date of Assignment:	22/12/2021	
Date Inspected:	22/12/2021 Inspected At:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building Singapore 659578
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP N/S	Cut	763.97 FL	*763.97 FL
2	1		*FRONT HEADLAMP TOP GRILLE N/S	Cracked	269.93 FL	*269.93 FL
3	1		*FRONT FOG LAMP (OUTER) N/S	Cracked	282.73 FL	*282.73 FL
4	1		*FRONT FOG LAMP (SMALL) N/S	Cut	266.81 FL	*266.81 FL
5	1		*FRONT BUMPER N/S	Cracked	764.91 FL	*764.91 FL
6	1		*FRONT STEP ALUMINIUM N/S	Dented	542.90 FL	*542.90 FL
7	1		*FRONT FOG LAMP BRACKET N/S	Not Necessary	387.34 FL	*- FL
8	1		*FRONT REFORCEMENT	Bent	3,927.00 FL	*3,927.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	7,205.59	6,818.25
- List Item Discount on L Items 10.00/10.00% (S\$)	720.56	681.83
Total Parts (S\$)	6,485.03	6,136.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPLACE ,REPAIR & WELD REAR DAMAGED PARTS	New	900.00	500.00
2	TO R&R LIGHT WIRING	New	80.00	30.00
3	TO PUTTY & SPRAY PAINTING	New	600.00	450.00
Gross Labour Cost (\$)			1,580.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >