

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012914/TPS3Q2**Date:** 09/03/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900083356
Claimant Vehicle No :	SHD6726J	Insured Vehicle No :	SMK3774T
Date of Loss:	20/12/2021	Nature of Claim:	TP
		Claim No:	7291106951SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6726J	Engine No:	G4LEKU415592
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVLU191624
Reg. Date:	30/10/2020 (Man. Year: 2019)	Odometer:	131688 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,682.80	1,013.52	669.28	39.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	840.00	630.00	210.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,522.80	1,643.52	879.28	34.85
+ GST 7.00/7.00% (S\$)	176.60	115.05	61.55	34.85
Nett Amount (S\$)	2,699.40	1,758.57	940.83	34.85
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$125.19/day) (S\$)		312.98		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,198.55		
Global Sum Settlement (S\$)		2,190.00		

INSPECTION

Date of Assignment:	20/12/2021	
Date Inspected:	20/12/2021	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Torn	459.40 FL	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY	Deformed	451.25 FL	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	394.80 FL	*- FL
5	1		*REAR BUMPER LOWER CTR MOULDIG	Not Necessary	155.00 FL	*- FL
6	1		*ANTENNA SMARTKEY	Cracked	40.50 FL	*40.50 FL
7	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
8	1		*LICENCE LAMP	Not Necessary	85.30 FL	*- FL
9	1		*REAR NUMBER PLATE WITH TRIM COVER	Cracked	55.00 FS	*55.00 FS
10	1		*REAR BUMPER REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS
					Sub Total (\$)	2,044.75 1,208.15
					- List Item Discount on L Items 20.00/20.00% (\$)	361.95 194.63
					Total Parts (\$)	1,682.80 1,013.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE	New	300.00	250.00
3	CHECK ALL LIGHTING	New	60.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
Gross Labour Cost (\$\$)			840.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >