

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012915/REA3Q2**Date:** 03/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100486408
Claimant Vehicle No :	SCF6980P	Insured Vehicle No :	SBK90H
Date of Loss:	16/12/2021	Nature of Claim:	TP
		Claim No:	1321057773SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCF6980P	Engine No:	G4FGFH771348
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFX411MF5420787
Reg. Date:	29/05/2015 (Man. Year: 2015)	Odometer:	131069 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,666.00	840.00	826.00	49.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	980.00	1,120.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,766.00	1,820.00	1,946.00	51.67
+ GST 7.00/7.00% (S\$)	263.62	127.40	136.22	51.67
Nett Amount (S\$)	4,029.62	1,947.40	2,082.22	51.67
+ Car Rental (6.0 x S\$100.00/day + 7.00% GST) (S\$)		642.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,591.40		

INSPECTION

Date of Assignment:	21/12/2021		
Date Inspected:	06/01/2022	Inspected At:	CYCLE & CARRIAGE KIA PTE LTD 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*COVER -RR BUMPER	Deformed	791.00 FS	*632.80 FS
3	1		*COVER -RR BUMPER UPR	Deformed	234.00 FS	*187.20 FS
4	1		*BEAM -RR BUMPER	Not Necessary	365.00 FS	*- FS
5	1		*STAY -RR BUMPER RH	Not Necessary	75.00 FS	*- FS
6	1		*STAY -RR BUMPER LH	Not Necessary	75.00 FS	*- FS
7	1		*BRACKET -RR BUMPER SIDE MTG ,RH	Not Necessary	33.00 FS	*- FS
8	1		*BRACKET -RR BUMPER SIDE MTG ,LH	Not Necessary	33.00 FS	*- FS
9	1		*C&C LOGO	Not Necessary	40.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					1,666.00	840.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER ,REPAIR REAR END PANEL ,BOOTLID	New	800.00	400.00
2	REMOVE & INSTALL PARKING SENSOR	New	100.00	80.00
3	SPRAY PAINT FOR REAR BUMPER ,BOOTLID ,REAR END PANEL	New	1,050.00	350.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELETRONIC CONTROL SYSTEM	New	120.00	120.00
Gross Labour Cost (\$\$)			2,100.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >