

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURA	NCE BHD	Re	f: CS3/LPC21003536/Rqf3e2-1	
	300 BEACH ROAD #17-04/07 THE CO) NCOURSESINGAPORE 199555	Da	ite: 23/02/2022	
			Co	de: LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 4579R	Veh. Inspected	GBB 7161M	
	Policy No.	Z/20/VC00/108728	Coverage (\$)	0.00	
	Claim No.	20/21/21/VC00/024339	Excess (\$)	0.00	
	Assign From	KENNY LIM	Assign Date	21/12/2021	
2.	Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150 M	c.c	2982	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	JTFAT35Y20K201003	Colour	GREY	
	Odometer	349071 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195 R15C	BRIDGESTONE	7 mm	
	L/H Front Tyre	195 R15C	BRIDGESTONE	7 mm	
	R/H Rear Tyre	155 R12C (D)	BRIDGESTONE	5/5 mm	
	L/H Rear Tyre	155 R12C (D)	BRIDGESTONE	5/5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	15/03/2021	Inspection Date	18/03/2021	
	Survey held at	EMPIRE IMAGE			
		NO.4 PANDAN LOOP (BLK K / BLK 1) SINGAPORE 128222			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	10	Working Days	