

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21012917/T1TF3E2

Date: 31/12/2021

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ002428		
Claimant Vehicle No :	SHA1942A	Insured Vehicle No :	GBA122C		
Date of Loss:	18/12/2021	Nature of Claim:	TP	Claim No:	M2105884

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1942A	Engine No:	D4FDGU625907
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU089955
Reg. Date:	26/05/2016 (Man. Year: 2016)	Odometer:	535546 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,740.10	932.40	807.70	46.42
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,020.00	560.00	460.00	45.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,771.10	1,503.40	1,267.70	45.75
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	2,771.10	1,200.00	1,571.10	56.70
+ GST 7.00/7.00% (S\$)	193.98	84.00	109.98	56.70
Nett Amount (S\$)	2,965.08	1,284.00	1,681.08	56.70

INSPECTION

Date of Assignment:	21/12/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	20/12/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Dec 2021)
Parts:	143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1942A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Reference	Amount
1	1	*REAR BUMPER	Deformed	553.00 FL	-	*553.00 FL
2	1	*REAR BUMPER REINFORCEMENT	Not Necessary	428.40 FL	-	*- FL
3	1	*REAR BUMPER SPONGE	Not Necessary	119.50 FL	-	*- FL
4	10	*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
5	1	*BOOTLID H EMBLEM	Not Necessary	63.10 FL	-	*- FL
6	1	*BOOTLID CRDI EMBLEM	Not Necessary	52.40 FL	-	*- FL
7	1	*BOOTLID I40 EMBLEM	Not Necessary	67.90 FL	-	*- FL
8	1	*BOOTLID COMFORTDELGRO STICKER	Not Necessary	15.00 F	-	*- F
9	1	*BOOTLID 65521111 STICKER	Not Necessary	15.00 F	-	*- F
10	1	*REAR BUMPER MAT	Necessary	50.00 FL	-	*50.00 FL
11	1	*REAR BUMPER UNDER COVER	Deformed	228.00 FL	-	*228.00 FL
12	2	*REAR BUMPER REINFORCEMENT BRACKET RH / LH	Not Necessary	71.20 FL	-	*- FL
13	1	*REAR BUMPER ADVERTISEMENT STICKER	Necessary	50.00 F	-	*50.00 F
14	2	*REAR FENDER ADVERTISEMENT STICKER RH / LH	Necessary	200.00 F	-	*200.00 F
15	1	*REVERSE SENSORS	Not Necessary	135.70 F	-	*- F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,071.20	1,103.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	331.10	170.60
Total Parts (\$\$)	1,740.10	932.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	280.00
2	SPRAY PAINTING	New	600.00	250.00
3	R/I REVERSE SENSORS	New	120.00	30.00
Gross Labour Cost (\$\$)			1,020.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >