

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012918/EVCE2

Date: 17/02/2022

REFERENCE

Insured/Claimant:	KIRAN PAL SINGH	Policy No:	2070016788		
Date of Loss:	18/12/2021	Nature of Claim:	OD	Claim No:	2367986376SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX169R		
Make & Model:	KIA STINGER, 2.0 2WD SUNROOF (A)	Engine No:	G4CLKH027498
Reg. Date:	19/02/2020 (Man. Year: 2019)	Chassis No:	KNAE351AML6080066
Colour:	White	Odometer:	50426 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$153,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R19	Rear Tyre Size:	245/40Z R19
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,293.00	16,820.80	9,472.20	36.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,520.00	3,470.00	1,050.00	23.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,813.00	20,290.80	10,522.20	34.15
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	29,213.00	18,690.80	10,522.20	36.02
+ GST 7.00/7.00% (S\$)	2,044.91	1,308.36	736.55	36.02
Nett Amount (S\$)	31,257.91	19,999.16	11,258.75	36.02

INSPECTION

Date of Assignment:	21/12/2021	
Date Inspected:	20/12/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	10.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FRT NUMBER PLATE FRAME	Cut	50.00 FS	*50.00 FS
3	1		*FRT LEFT TYRE AND REAR LEFT TYRE	Front O/S Torn	1,160.00 FS	*580.00 FS
4	1		*COVER-FR BUMPER	Broken	646.00 F	*646.00 FL
5	1		*LOGO ASSY-KIA SUB	Necessary	45.00 F	*45.00 FL
6	1		*GRILLE-FRONT BUMPER	Cut	391.00 F	*391.00 FL
7	1		*GRILLE ASSY-RADIATOR	Cut	444.00 F	*444.00 FL
8	1		*ABSORBER-FRONT BUMPER ENERGY	Broken	105.00 F	*105.00 FL
9	1		*COVER ASSY-AIR CURTAIN, RH	Broken	126.00 F	*126.00 FL
10	1		*LIP ASSY-FRONT BUMPER	Cut	22.00 F	*22.00 FL
11	1		*MOULDING-FRT BPR LICENSE PLATE	Crushed	35.00 F	*35.00 FL
12	1		*CAP-FRONT HOOK	Crushed	9.00 F	*9.00 FL
13	1		*COVER ASSY-RADIATOR GRILLE, UPR	Not Necessary	72.00 F	*- FL
14	1		*COVER ASSY-FENDER SIDE, RH	Not Necessary	13.00 F	*- FL
15	1		*STIFFNER-FR BPR LWR	Broken	127.00 F	*127.00 FL
16	1		*BRACKET-FR BUMPER MOUNTING RH	Not Necessary	10.00 F	*- FL
17	1		*BRKT ASSY-FRT BUMPER SIDE MTG	Broken	15.00 F	*15.00 FL
18	1		*BRACKET-FR BUMPER SIDE, LH	Not Necessary	15.00 F	*- FL
19	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	189.00 F	*- FL
20	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	159.00 F	*- FL
21	1		*BEAM COMPLETE-FR BUMPER	Dented	620.00 F	*620.00 FL
22	1		*CARRIER ASSY-FRONT END MODULE	Broken	697.00 F	*697.00 FL
23	1		*TENSION ARM ASSY-FRT, RH	Not Necessary	644.00 F	*- FL
24	1		*LATERAL ARM ASSY-FRONT	Not Necessary	535.00 F	*- FL
25	1		*COVER ASSY-COWL TOP	Not Necessary	216.00 F	*- FL
26	1		*GLASS ASSY-WINDSHIELD	Broken	2,009.00 F	*2,009.00 FL
27	1		*MOULDING-WINDSHIELD GLASS	Necessary	92.00 F	*92.00 FL
28	1		*MOULDING ASSY-W/SHLD SIDE, RH	Necessary	94.00 F	*94.00 FL
29	1		*MOULDING ASSY-W/SHLD SIDE, LH	Necessary	94.00 F	*94.00 FL
30	1		*BRACKET-W/S MLDG MTG, RH	Necessary	27.00 F	*27.00 FL
31	1		*BRACKET-W/S MLDG MTG, LH	Necessary	27.00 F	*27.00 FL
32	1		*LAMP ASSY-HEAD, RH	Cut	3,977.00 F	*3,977.00 FL
33	1		*EXTN WIRING ASSY-SPAS	Not Necessary	194.00 F	*- FL
34	1		*WIRING ASSY-FEM	Necessary	256.00 F	*256.00 FL
35	2		*SENSOR ASSY-A TYPE CRASH	Necessary	192.00 F	*192.00 FL
36	1		*MODULE ASSY-AIR BAG CONTROL	Necessary	810.00 F	*810.00 FL
37	2		*SENSOR ASSY-PRESS TYPE CRASH	Not Necessary	230.00 F	-
38	1		*MODULE ASSY-KNEE AIR BAG	Broken	595.00 F	*595.00 FL
39	1		*AIR BAG ASSY-PASSENGER	Broken	1,163.00 F	*1,163.00 FL
40	1		*MODULE ASSY-STRG WHEEL AIR BAG	Broken	1,516.00 F	*1,516.00 FL
41	1		*SENSOR-ANGULAR VELOCITY	Necessary	375.00 F	*375.00 FL
42	1		*CONTACT ASSY-CLOCK SPRING	Necessary	169.00 F	*169.00 FL
43	1		*CRASH PAD ASSY-MAIN	Broken	2,146.00 F	*2,146.00 FL
44	1		*PAD-CRASH PAD MAIN	Not Necessary	15.00 F	*- FL
45	1		*GUARD-AIR	Broken	88.00 F	*88.00 FL
46	1		*COOLER ASSY-OIL	Not Necessary	391.00 F	*- FL
47	1		*VALVE-BYPASS	Not Necessary	205.00 F	*- FL
48	1		*TUBE ASSY-OIL COOLER	Not Necessary	307.00 F	*- FL
49	1		*CONDENSER ASSY-COOLER	Not Necessary	805.00 F	*- FL
50	1		*RADIATOR ASSY	Not Necessary	699.00 F	*- FL
51	1		*SENSOR & UNIT ASSY-ACTIVE HOOD	Torn	936.00 F	*936.00 FL
52	1		*LATCH ASSY-HOOD	Not Necessary	114.00 F	*- FL
53	1		*STRIP ASSY-HOOD SEAL	Not Necessary	25.00 F	*- FL
54	1		*S/BELT ASSY-FR RH	Jammed	420.00 F	*420.00 FL
55	1		*S/BELT ASSY-FR LH	Jammed	420.00 F	*420.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SEAT BELT PRETENSIONER, RH	Necessary	194.00 F	*194.00 FL
57	1		*SEAT BELT PRETENSIONER, LH	Necessary	194.00 F	*194.00 FL
58	1		*S/BELT ASSY-RR, RH	Jammed	398.00 F	*398.00 FL
59	1		*S/BELT ASSY-RR, LH	Jammed	398.00 F	*398.00 FL
60	1		*BRACKET, IU ADHESIVE	Necessary	26.00 FS	*26.00 FS
61	1		*BRACKET-FR BUMPER SIDE SUPT, RH	Not Necessary	18.00 F	*- FL
62	1		*PANEL-UNDER COVER FROM (Supplementary)	Broken	283.00 F	*283.00 FL
63	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 F	*26.00 FL
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					26,293.00	20,857.00
- List Item Discount on L Items 0.00/20.00% (\$\$)					0.00	4,036.20
Total Parts (\$\$)					26,293.00	16,820.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT SUPPORT PANEL, REPAIR BONNET, FRT FENDER RH	New	1,600.00	600.00
2	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
3	TOP UP AIRCON GAS	New	80.00	80.00
4	SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH	New	1,050.00	1,050.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
7	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
8	TRANSFER FRT & REAR LEFT TYRE	New	60.00	30.00
9	RENEW FRT DASHBOARD AND AIRBAG SYSTEM	New	400.00	400.00
10	RENEW FRT & BACK SEAT BELTS & IMPACT SENSOR	New	400.00	400.00
11	RENEW FRT WINDSCREEN	New	240.00	240.00
12	APPLY SEALANT FOR FRT WINDSCREEN	New	80.00	80.00
13	RENEW FRT WINDSCREEN SOLAR FILM	New	240.00	220.00
Gross Labour Cost (\$\$)			4,520.00	3,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >