1/12/22, 8:53 AM Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21012919/GTF3N2

12/01/2022 Date:

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070118257 **Claimant Vehicle** 

SJB5783L Insured Vehicle No: SMU3719B No:

Date of Loss: 17/12/2021 Nature of Claim: TP Claim No: 6091211905SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SJB5783L

TOYOTA AXIO, 1.5 (A) Make & Model: **Engine No:** 1NZC780370 Reg. Date: 17/01/2008 (Man. Year: 2007) Chassis No: NZE1416054646 Colour: Odometer: 267106 km Silver

**Engine Capacity:** 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 185/70R14 Rear Tyre Size: 185/70R14 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 21/12/2021

Esl Automotive Pte Ltd (HQ)

25 Kaki Bukit Road 4, #07-47 & #07-75 Synergy Date Inspected: 21/12/2021 Inspected At:

@KB

Singapore 417800

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG DENISE TAY KWEE CHENG Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE: \$7,600.00 (EST)

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty Part No	. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Dented	0.00 F	*- F
2	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2	*REAR BUMPER BRACKET	Dented	0.00 F	*- F
4	2	*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1	*REVERSE SENSOR	Damaged	0.00 F	*- F
6	1	*REAR END PANEL	Buckled	0.00 F	*- F
7	1	*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
8	1	*REAR LH TAILLAMP	Broken	0.00 F	*- F
9	1	*REAR LH TAILLAMP PANEL	Repair	0.00 F	*- F
10	1	*REAR RH TAILLAMP	Cracked	0.00 F	*- F
11	1	*BOOTLID	Buckled	0.00 F	*- F
12	2	*BOOTLID EMBLEM	Necessary	0.00 F	*- F
13	1	*BOOTLID LOCK	Bent	0.00 F	*- F
14	1	*BOOTLID RUBBER	Bent	0.00 F	*- F
15	2	*BOOTLID HINGE	Bent	0.00 F	*- F
16	1	*SPARE TYRE BOARD	Torn	0.00 F	*-F
17	1	*TOOLS HOLDER	Bent	0.00 F	*-F
F=Fra	nchise part.		_		
			Total Parts (S\$)	0.00	0.00
		Report was unsubmitted du	uring this print-out.		

Adjuster Report

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >