

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012921/AVY3M4**Date:** 10/07/2023**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00024432100		
<b>Claimant Vehicle No :</b>	SJE9020M	<b>Insured Vehicle No :</b>	SJE184H		
Date of Loss:	20/12/2021	Nature of Claim:	TP	Claim No:	SNM21D207426/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SJE9020M</b>	Engine No:	BLG051689
Make & Model:	VOLKSWAGEN GOLF, 1.4 GT TSI (A)	Chassis No:	WVWZZZ1KZ8U023861
Reg. Date:	12/05/2008 (Man. Year: 2008)	Odometer:	207576 km
Colour:	Blue		
Engine Capacity:	1390 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,830.98	7,019.79	7,811.19	52.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	2,140.00	800.00	27.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,770.98</b>	<b>9,159.79</b>	<b>8,611.19</b>	<b>48.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,300.00</b>		
<b>(S\$)</b>	17,770.98	7,300.00	10,470.98	58.92
<b>+ GST 8.00/8.00% (S\$)</b>	1,421.68	584.00	837.68	58.92
<b>Nett Amount (S\$)</b>	<b>19,192.66</b>	<b>7,884.00</b>	<b>11,308.66</b>	<b>58.92</b>

**INSPECTION**

Date of Assignment:	22/12/2021		
Date Inspected:	21/12/2021	Inspected At:	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921
Estimated Period of Repair:	6.0 days		

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2023)
Parts:	143	VOLKSWAGEN GOLF 1.4 GT TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE9020M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Repair	1,999.70 F	*- FL
2	1		*FRONT LH DOOR PROTECTOR	Cut	188.96 F	*188.96 FL
3	1		*FRONT LH DOOR WEATHER STRIP	Not Necessary	300.93 F	*- FL
4	1		*REAR BUMPER	Torn	1,800.97 F	*1,800.97 FL
5	1		*REAR BUMPER LOWER LID	Cut	300.97 F	*300.97 FL
6	1		*REAR BUMPER RETAINER L/R	N/S Necessary	199.40 F	*99.70 FL
7	1		*REAR LH CONTROL ARM	Bent	487.60 F	*487.60 FL
8	1		*REAR LH DOOR	Dented	1,988.60 F	*1,655.00 FL
9	1		*REAR LH DOOR HINGE (LOWER)	Not Necessary	190.77 F	*- FL
10	1		*REAR LH DOOR PROTECTOR	Not Necessary	189.86 F	*- FL
11	1		*REAR LH DOOR WEATHER STRIP	Necessary	300.93 F	*300.93 FL
12	1		*REAR LH FENDER	Repair	1,699.07 F	*- FL
13	1		*REAR LH FENDER INNER SHIELD	Not Necessary	200.97 F	*- FL
14	1		*REAR LH KNUCKLE ARM	Damaged	688.70 F	*688.70 FL
15	1		*REAR LH KNUCKLE ARM BEARING	Damaged	688.99 F	*498.00 FL
16	1		*REAR LH LOWER ARM	Bent	399.70 F	*399.70 FL
17	1		*REAR LH SHOCK ABSORBER	Bent	189.97 F	*189.97 FL
18	1		*REAR LH STABILIZER LINK	Not Necessary	130.77 F	*- FL
19	1		*REAR LH TRAILING ARM	Bent	433.71 F	*433.71 FL
20	1		*REAR LH UPPER ARM	Not Necessary	499.70 F	*- FL
21	1		*REAR LH SPORT RIM	Cut	1,300.71 FS	*650.00 FS
22	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
23	1		*REAR LH 225/40ZR18 TYRE	Not Necessary	550.00 FS	*- FS
24	1		*SET REAR LH FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,830.98	7,724.21
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	704.42
Total Parts (\$\$)	14,830.98	7,019.79

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	50.00
2	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC	New	280.00	220.00
3	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	100.00	80.00
4	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	100.00	50.00
5	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE	New	160.00	80.00
6	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,100.00	1,000.00
7	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	600.00
8	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>2,940.00</b>	<b>2,140.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >