

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD	Ref:	CS3/ASM21012925/Vty3e2	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	31/12/2021	
	ATTN: KITTY TEO		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMP 7241L	Veh. Inspected	SMM 4184D	
	Policy No.	VFX/P2440417	Coverage (\$)	0.00	
	Claim No.	S1M03OR5	Excess (\$)	0.00	
	Assign From	KITTY TEO	Assign Date	21/12/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FIT HYBRID	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	GP51334772	Colour	BLACK	
	Odometer	178667 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/55 R15	TRISTAR	5 mm	
	L/H Front Tyre	195/55 R15	TRISTAR	5 mm	
	R/H Rear Tyre	195/55 R15	TRISTAR	5 mm	
	L/H Rear Tyre	195/55 R15	TRISTAR	5 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information				
	Accident Date	17/12/2021	Inspect Date / Time	21/12/2021 (02:00 PM)	
	Survey held at	GALAXY AUTO CARE PTE LTD			
	13 KAKI BUKIT ROAD 4 #01-23 BARTLEY BIZ CENTRE SINGAPORE 417807				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b.	b. Estimate Days of Repair				

Report Ref No. CS3/ASM21012925/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

4 Working Days