

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21012928/T1TF3N2
Date: 29/12/2021REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ005301
Claimant Vehicle No :	SHC1503Z	Insured Vehicle No :	GBK8128G
Date of Loss:	16/12/2021	Nature of Claim:	TP
		Claim No:	M2105855

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1503Z	Engine No:	G4LEJU032240
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU114731
Reg. Date:	08/10/2018 (Man. Year: 2018)	Odometer:	434612 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,463.96	828.52	635.44	43.41
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	750.00	640.00	110.00	14.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,224.96	1,479.52	745.44	33.50
Approved Total (Overridden) (S\$)		1,200.00		

	(S\$)	2,224.96	1,200.00	1,024.96	46.07
	+ GST 7.00/7.00% (S\$)	155.75	84.00	71.75	46.07
	Nett Amount (S\$)	2,380.71	1,284.00	1,096.71	46.07

INSPECTION

Date of Assignment: 21/12/2021

Date Inspected: 20/12/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2021)
Parts: 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC1503Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER ASSY	Cracked	459.40 FL	-	*459.40 FL
2	10		*REAR BUMPER CLIPS	Necessary	220.00 FL	-	*220.00 FL
3	1		*REAR BUMPER BEAM	Not Necessary	394.80 FL	-	*- FL
4	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	-	*451.25 FL
5	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	-	*- FL
6	1		*ANTENNA ASSY - SMARTKEY	Cracked	40.50 FL	-	*40.50 FL
7	1		*REAR NUMBER PLATE	Cracked	50.00 F	-	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,817.45	1,023.15
- List Item Discount on L Items 20.00/20.00% (S\$)	353.49	194.63
Total Parts (S\$)	1,463.96	828.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	50.00	40.00
			Gross Labour Cost (\$)	750.00
				640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >