

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21012929/KQY3N2**Date:** 08/02/2022REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMB1SNW00009012102

**Claimant Vehicle  
No :** GBB4086S**Insured Vehicle  
No :** CB6756S

Date of Loss: 10/12/2021

Nature of Claim: TP

Claim  
No: SNM21D207259/C02/CSCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBB4086S**

Make &amp; Model: RENAULT KANGOO, 1.4 (A)

Engine No: K9KW714D207738

Reg. Date: 23/02/2009 (Man. Year: 2007)

Chassis No: VF1FC1EAF38795251

Colour: White

Odometer: 129305 km

Engine Capacity: 1461 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 165/70 R14

Rear Tyre Size:

165/70 R14

Front Left Side: Davanti 8 mm

Rear Left Side:

Kumho 4 mm

Front Right Side: Davanti 8 mm

Rear Right Side:

Kumho 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,559.50	2,389.59	1,169.91	32.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,950.00	810.00	1,140.00	58.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,509.50</b>	<b>3,199.59</b>	<b>2,309.91</b>	<b>41.93</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,550.00</b>		
<b>(S\$)</b>	5,509.50	2,550.00	2,959.50	53.72
<b>+ GST 7.00/7.00% (S\$)</b>	385.67	178.50	207.17	53.72
<b>Nett Amount (S\$)</b>	<b>5,895.17</b>	<b>2,728.50</b>	<b>3,166.67</b>	<b>53.72</b>

INSPECTION

Date of Assignment: 21/12/2021

Date Inspected: 16/12/2021 Inspected At:

ComfortDelGro Engineering Pte Ltd (Braddell)  
205 Braddell Road  
Singapore 579701

Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 Feb 2022)
<b>Parts:</b>	144	RENAULT KANGOO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBB4086S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	745.00 F	*685.60 FN
2	1		*REAR BUMPER LH COVER	Serviceable	340.00 F	*- FN
3	1		*LH BACK DOOR	Bent	1,149.50 F	*1,149.50 FN
4	1		*LH BACK DOOR GLASS	Shattered	340.00 F	*340.00 FN
5	1		*LH BACK DOOR GLASS WEATHER STRIP	Necessary	220.00 F	*220.00 FN
6	1		*LH BACK DOOR LOWER GARNISH	Bent	300.00 F	*170.00 FN
7	1		*LH BACK DOOR RENAULT EMBLEM	Necessary	170.00 F	*90.00 FN
8	1		*REVERSE SENSOR	Serviceable	250.00 FS	*- FS
9	1		*REAR NO PLATE W/CASING (SILVER/EMBOSS)	Serviceable	45.00 FS	*- FS
					<b>Sub Total (\$\$)</b>	<b>3,559.50 2,655.10</b>
					<b>- Nett Item Discount on N Items 0.00/10.00% (\$\$)</b>	<b>0.00 265.51</b>
					<b>Total Parts (\$\$)</b>	<b>3,559.50 2,389.59</b>

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO KNOCK,STRAIGHTEN AND RENEW ACCIDENT AREA SUCH REAR BUMPER,REAR LH DOOR,REPAIR REAR END PANEL AND AFFECTED AREA	New	1,000.00	480.00
2	TO PUTTY AND RESPRAY ON REAR BUMPER,REAR LH BACK DOOR AND AFFECTED AREA	New	800.00	250.00
3	TRANSFER PART TO NEW DOOR	New	150.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,950.00</b>	<b>810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >