

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21012931/VPA3Q2
Date: 20/10/2022

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100478274
Claimant Vehicle No :	SMG4840A	Insured Vehicle No :	SDA980T
Date of Loss:	18/12/2021	Nature of Claim:	TP
		Claim No:	4026079727SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG4840A		
Make & Model:	MINI COOPER, 1.5 (A)	Engine No:	38995049B38A15A
Reg. Date:	29/09/2017 (Man. Year: 2017)	Chassis No:	WMWYS320303E12116
Colour:	Blue	Odometer:	59874 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,959.50	10,205.00	3,754.50	26.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,590.00	1,430.00	2,160.00	60.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	17,549.50	11,635.00	5,914.50	33.70
+ GST 7.00/7.00% (\$\$)	1,228.47	814.45	414.02	33.70
Nett Amount (\$\$)	18,777.97	12,449.45	6,328.52	33.70
+ Loss of Use (4.0 x \$60.00/day) (\$\$)		240.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		12,691.45		

INSPECTION

Date of Assignment:	21/12/2021		
Date Inspected:	22/12/2021	Inspected At:	Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443
Estimated Period of Repair:	4.0 days		

Adjuster: Thevan Thomas Karthikesavan

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	800.00 FL	*800.00 FL
2	2		*FRONT BUMPER N/S & O/S SIDE RETAINER	Necessary	340.00 FL	*340.00 FL
3	1		*FRONT BUMPER TOW HOOK COVER	Cut	50.00 FL	*50.00 FL
4	1		*BONNET GRILLE	Cut	360.00 FL	*360.00 FL
5	1		*FRONT BUMPER CENTRE GRILLE	Cut	70.00 FL	*70.00 FL
6	1		*FRONT BUMPER LOWER COVER	Distorted	400.00 FL	*400.00 FL
7	1		*FRONT BUMPER LOWER STIFFER	Serviceable	80.00 FL	*- FL
8	2		*FRONT BUMPER N/S & O/S FOG LAMP	Serviceable	340.00 FL	*- FL
9	2		*FRONT BUMPER N/S & O/S FOG LAMP BEZEL	Cut	220.00 FL	*220.00 FL
10	1		*FRONT BUMPER SPONGE	Serviceable	65.00 FL	*- FL
11	1		*FRONT BUMPER REINFORCEMENT	Dented	590.00 FL	*590.00 FL
12	1		*SUPPORT PANEL	Serviceable	350.00 FL	*- FL
13	1		*SUPPORT PANEL SIDE AIR GRILLE LH (NO 2)	Serviceable	40.00 FL	*- FL
14	1		*AIR DUCT LH (NO3)	Cut	570.00 FL	*570.00 FL
15	1		*RADIATOR	Serviceable	600.00 FL	*- FL
16	1		*INTERCOOLER	Serviceable	500.00 FL	*- FL
17	1		*AIR-CON CONDENSOR	Serviceable	800.00 FL	*- FL
18	1		*BLOWER FAN ASSY	Serviceable	800.00 FL	*- FL
19	2		*FRONT N/S & O/S HEADLAMP	Cracked	6,000.00 FL	*6,000.00 FL
20	2		*FRONT N/S & O/S HEADLAMP BEZEL	Cracked	280.00 FL	*280.00 FL
21	2		*FRONT N/S & O/S HEADLAMP SIDE SUPPORT BRACKET	Serviceable	40.00 FL	*- FL
22	1		*BONNET LOGO	Necessary	190.00 FL	*190.00 FL
23	1		*BONNET	Dented	1,200.00 FL	*1,200.00 FL
24	2		*BONNET N/S & O/S LOCK	Serviceable	150.00 FL	*- FL
25	2		*BONNET N/S & O/S HINGES	Serviceable	220.00 FL	*- FL
26	1		*FRONT N/S WHEELARCH TRIM	Distorted	180.00 FL	*180.00 FL
27	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*30.00 FS
28	1		*SET FRONT NO PLATE WITH CASING	Necessary	50.00 FS	*50.00 FS
29	1		*SET COOLANT	Not Necessary	100.00 FS	*- FS
30	1		*SUNDRY	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,483.00	11,330.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,523.50	1,125.00
Total Parts (\$\$)	13,959.50	10,205.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO ADJUST /FOCUS /RESET FRONT HEADLAMPS	New	350.00	0.00
3	TO CHECK /TOP UP AIR-CON GAS	New	80.00	0.00
4	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT CARPET ETC TO FACILITATE REPAIRS	New	180.00	60.00
5	LABOUR CHARGE FOR DISMANTLE AND REPLACE THE ACCIDENT DAMAGED PARTS .INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF BONNET ,FRONT BUMPER ,FRONT N/S & O/S FENDER ,SUPPORT PANEL ETC	New	1,500.00	700.00
6	TO PUTTY AND SPRAY PAINTING ON BONNET ,FRONT BUMPER ,FRONT N/S & O/S FENDER	New	1,200.00	600.00
7	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	200.00	40.00
Gross Labour Cost (\$\$)			3,590.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >