## PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

22-Dec-21

| 1 pc   | Front bumper / ŊĨ                                     | ~        |    |          |   |
|--------|---|----------|----|----------|---|
| 2 pcs  | Front bumper n/s & o/s side retainer                  |          |    |          |   |
| 1 pc   | Front bumper tow hook cover / Cut                     |          |    |          |   |
| 1 pc   | Bonnet grille / Cut                                   |          |    |          |   |
| 1 pc   | Front bumper centre grille / (NF                      |          |    |          |   |
| 1 pc   | Front bumper lower cover > 1)t 5                      |          |    |          |   |
| 1 pc   | Front bumper lower stiffer .                          |          |    |          |   |
| 2 pcs  | Front bumper n/s & o/s fog lamp                       |          |    |          |   |
| 2 pcs  | Front bumper n/s & o/s fog lamp Mexen (U+ SU          |          |    |          |   |
| 1 pc   | Front bumper sponge 1 Cover                           |          |    |          |   |
| 1 pc   | Front bumper reinforcement ().                        |          |    |          |   |
| 1 pc   | Support panel 1.                                      |          |    |          |   |
| 1 pc   | Support panel side air grille LH (no 2)               |          |    |          |   |
| 1 pc   | Air duct LH (no 3) 1,                                 |          |    |          |   |
| 1 pc   | Radiator 1.   |          |    |          |   |
| 1 pc   | Intercooler 1   |          |    |          |   |
| 1 pc   | Air-con condensor                                     |          |    |          |   |
| 1 pc   | Blower fan assy 1                                     |          |    |          |   |
| 2 pcs  | Front n/s & o/s headlamp                              |          |    |          |   |
| 2 pcs  | Front n/s & o/s headlamp bezel                        |          |    |          |   |
| 2 pcs  | Front n/s & o/ş-headlamp side support bracket         |          |    |          |   |
| 1 pc   | Bonnet logo / nec                                     |          |    |          |   |
| 1 pc   | Bonnet / () (   |          |    |          |   |
| 2 pcs  | Bonnet n/s & o/s lock 💥 ປ C                           |          |    |          |   |
| 2 pcs  | Bonnet n/s & o/s hinges χ <sup>ζ</sup> ν <sup>C</sup> |          |    |          |   |
| 1 pc   | Front n/s wheelarch trim / DT 9                       |          |    |          | 7 |
|        |   |          | \$ |          | • |
|        |   | Less 10% | \$ |          |   |
|        |   |          | \$ |          |   |
|        |   |          | •  |          |   |
|        |   |          |    |          |   |
| S/NETT |   |          |    |          |   |
| 1 set  | Front bumper clips                                    |          | \$ | 48.00 30 |   |
| 1 set  | Front no. plate with casing                           |          | \$ | 50.00    |   |
| 1 set  | Coolant   |          | \$ | 100.00 1 | / |
| . 551  |   |          | *  |          | / |

the married thank the transmit and making

22-Dec-21

A 4-1918 A 59 2784

## ESTIMATE REPAIR BILL FOR MINI COOPER REGN NO: SMG 4840 A

| Sundry  | \$ | 50.00X SX             |
|---|----|-----------------------|
| To check wiring   | 3  | 80.0030               |
| To adjust / focus / reset front headlamps   | \$ | 350.00 <b>44</b> V.   |
| To check / top up air-con gas   | \$ | 50 00 °C              |
| To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs   | \$ | 180.00 60             |
| Labour charge for dismantle and replace the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of bonnet, front bumper, front n/s & o/s fender, support panel, etc | \$ | 1,500.00 700          |
| To putty and spray painting on bonnet, front bumper, front n/s & o/s fenders  | \$ | 1,200.00 600          |
| To apply rustproofing on the repaired and replaced panels.  | \$ | 200.00 UO<br>3,838.00 |

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Therange Magnito. Com
82235769
22/12/21 / 1/100
P() dismantle
bir paint
Uclays wp

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: