

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNA 5216R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	DOOR PANEL FRT RH (SN)	BENT	3,581.40	3,581.40
1	DOOR SEAL FRT RH (SN)	NECESSARY	425.10	425.10
1	SIDE STEP RH (SN)	CRACKED	573.30	573.30
1	FENDER FRT RH (SN)	BENT	1,271.40	1,271.40
1	RIM (SN)	TO REPAIR SEE LABOUR	2,285.40	-
1	BONNET (SN)	TO REPAIR SEE LABOUR	2,798.90	-
1	SIDE MIRROR RH (SN)	CRACKED	3,645.20	3,645.20
			14,580.70	9,496.40
	<u>LABOUR</u>			
	TO REPLACE BONNET, FRT RH FENDER, FRT RH DOOR, REAR RH DOOR, RH WING MIRROR, SIDE STEP, ETC. INCLUSIVE OF THE REPAIR OF RIM AND BONNET.		6,000.00	1,500.00
	TO SPRAYPAINT ON BONNET, FRT RH FENDER, FRT RH DOOR, REAR RH DOOR, WING MIRROR COVER, REAR RH FENDER, ETC.		6,300.00	1,400.00
	TO REMOVE, REFIT & TRANSFER FRT RH DOOR COMPONENTS.		500.00	150.00
	TO REPLACE FRT RH RIM.	NOT NECESSARY	50.00	-
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		621.00	250.00
	WHEEL ALIGNMENT.		280.00	150.00
			13,751.00	3,450.00
	GRAND TOTAL		28,331.70	12,946.40

RECOMMENDED COST OF REPAIRS	12,946.40
-----------------------------	-----------

Report Ref No. CS/TP21012933/Rqf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X. Z.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.