

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012934/R1GA3Q2**Date:** 06/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070176605
Claimant Vehicle No :	SKP6613C	Insured Vehicle No :	SJV8628C
Date of Loss:	17/12/2021	Nature of Claim:	TP
		Claim No:	2078844573SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKP6613C	Engine No:	A3320702N20B20B
Make & Model:	BMW 520I, 2.0 (A)	Chassis No:	WBA5A32060D789326
Reg. Date:	30/09/2014 (Man. Year: 2013)	Odometer:	131121 km
Colour:	Black		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	285/30Z R20	Rear Tyre Size:	285/30Z R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,765.80	5,774.20	11,991.60	67.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	1,380.00	2,940.00	68.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,085.80	7,154.20	14,931.60	67.61
Approved Total (Overridden) (S\$)		5,700.00		
Nett Amount (S\$)	22,085.80	5,700.00	16,385.80	74.19
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,427.45		
Global Sum Settlement (S\$)		6,200.00		

INSPECTION

Date of Assignment:	21/12/2021	TEC AUTO SERVICES (HQ) 48 TOH GUAN ROAD EAST, #05-107, ENTERPRISE HUB Singapore 608586
Date Inspected:	22/12/2021 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,750.00 FL	*1,550.00 FL
2	1		*REAR BOOTLID CENTRE LOGO	Necessary	39.00 FL	*39.00 FL
3	2		*BOOTLID HINGE	Serviceable	115.00 FL	*- FL
4	2		*BOOTLID HINGE GARNISH	Serviceable	130.00 FL	*- FL
5	1		*BOOTLID WEATHERSTRIP	Serviceable	215.00 FL	*- FL
6	1		*BOOTLID LOCK ASSY	Serviceable	310.00 FL	*- FL
7	1		*BOOTLID LOCK CATCH	Serviceable	145.00 FL	*- FL
8	1		*BOOTLID CONTROL UNIT	Serviceable	1,050.00 FL	*- FL
9	1		*BOOTLID DAMPER LH	Serviceable	570.00 FL	*- FL
10	1		*BOOTLID DAMPER RH	Serviceable	570.00 FL	*- FL
11	1		*BOOTLID LAMP LH	Cracked	365.00 FL	*265.00 FL
12	1		*BOOTLID LAMP RH	Scratched	365.00 FL	*265.00 FL
13	1		*END PANEL	Serviceable	610.00 FL	*- FL
14	1		*END PANEL TOP GARNISH	Deformed	149.00 FL	*149.00 FL
15	1		*END PANEL LOCK SENSOR	Serviceable	75.00 FL	*- FL
16	1		*FLOOR PANEL COMPARTMENT	Serviceable	850.00 FL	*- FL
17	1		*REAR LUGGAGE COMPARTMENT	Not Necessary	110.00 FL	*- FL
18	1		*REAR FENDER INNER TRIM LH	Serviceable	250.00 FL	*- FL
19	1		*REAR FENDER INNER TRIM RH	Serviceable	250.00 FL	*- FL
20	2		*REAR BUMPER RETAINER	Not Necessary	95.00 FL	*- FL
21	1		*REAR BUMPER BRACKET CENTRE	Cracked	150.00 FL	*150.00 FL
22	1		*REAR BUMPER CENTRE UPPER HOLDER	Not Necessary	30.00 FL	*- FL
23	1		*REAR BUMPER CENTRE LOWER HOLDER	Not Necessary	30.00 FL	*- FL
24	1		*REAR BUMPER REINFORCEMENT	Bent	640.00 FL	*640.00 FL
25	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	145.00 FL	*- FL
26	1		*REAR BUMPER REFLECTOR LH	Cracked	45.00 FL	*45.00 FL
27	1		*REAR BUMPER REFLECTOR RH	Cracked	45.00 FL	*45.00 FL
28	4		*REAR PARKING SENSOR	Necessary (2 PCS ONLY)	1,332.00 FS	*400.00 FS
29	4		*REAR SENSOR HOLDER	Necessary	80.00 FL	*80.00 FL
30	1		*REAR EXHAUST ASSY	Serviceable	2,310.00 FL	*- FL
31	2		*REAR EXHAUST MOUNTING	Not Necessary	30.00 FL	*- FL
32	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	114.00 FL	*- FL
33	1		*EXTERNAL AERIAL COMFORT ACCESS	Necessary	550.00 FL	*210.00 FL
34	1		*REAR NUMBER PLATE	Not Necessary	90.00 FS	*- FS
35	1		*REAR BUMPER (AFTER MARKET)	Deformed	1,700.00 FS	*1,000.00 FS
36	1		*SET REAR TAILLAMP (AFTER MARKET)	Not Necessary	1,800.00 FS	*- FS
37	1		*SET BOOTLID INNER TRIM CLIP	Necessary	30.00 FS	*30.00 FS
38	1		*SET FENDER INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
39	1		*BOOTLID SPOILER	Necessary	500.00 FS	*250.00 FS
40	1		*JOINT SEALANT	Not Necessary	120.00 FS	*- FS
41	1		*M5 DIFFUSER	Cracked	500.00 FS	*300.00 FS
42	1		*STICKER WRAP	Necessary	700.00 FS	*700.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,984.00	6,118.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,218.20	343.80
Total Parts (\$\$)	17,765.80	5,774.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ALL WIRING AND LIGHTING SYSTEM	New	120.00	50.00
2	DIAGNOIS CHECK AND CLEAR FAULT CODE	New	500.00	200.00
3	REMOVE,REFIT REAR LINING ,TRIM AND GARNISH	New	200.00	60.00
4	REMOVE AND RENEW REAR SENSOR	New	120.00	60.00
5	REMOVE AND RENEW REAR EXHAUST ASSY	New	150.00	100.00
6	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	250.00	60.00
7	PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS	New	1,400.00	600.00
8	REMOVE AND RENEW WRAPPING ON AFFECTED AREAS	New	1,200.00	200.00
9	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	50.00
10	REPAIR EXHAUST LABOUE	New	180.00	0.00
Gross Labour Cost (\$\$)			4,320.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >