



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 4421L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	CRACKED	2,250.00	2,250.00
1	REAR BUMPER RH BRACKET	TO REPAIR SEE LABOUR	550.00	-
1	RH SIDE COMPARTMENT COVER	TO REPAIR SEE LABOUR	1,950.00	-
1	RH SIDE COMPARTMENT OUTER LOCK	DENTED	170.00	170.00
1	RH SIDE COMPARTMENT REFLECTOR LAMP	SERVICEABLE	185.00	-
	LESS 10% DISCOUNT		-	-242.00
			5,105.00	2,178.00
	<b><u>LABOUR</u></b>			
	CHECK WIRING.		20.00	20.00
	LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR BUMPER RH BRACKET AND RH SIDE COMPARTMENT COVER.		2,100.00	750.00
	ALIGNMENT OF RH SIDE COMPARTMENTS.	NOT NECESSARY	300.00	-
	SPRAY PAINTING WITH MULTI COLOR DESIGN AND LINING.		3,000.00	1,350.00
			5,420.00	2,120.00
<b>GRAND TOTAL</b>			<b>10,525.00</b>	<b>4,298.00</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,450.00</b>
---	--	--	-----------------

Report Ref No. CS/SMO21012951/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.