

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012953/UVY3N2**Date:** 24/02/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00124642101

Claimant Vehicle No : XD9398M **Insured Vehicle No :** GBC2770H

Date of Loss: 17/12/2021 Nature of Claim: TP Claim No: SNM21D207403/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **XD9398M**

Make & Model: MITSUBISHI FV51JJD4RDEA, 12.9 D (M) Engine No: 6M70453838

Reg. Date: 16/11/2012 (Man. Year: 2012) Chassis No: FV51JJA00941

Colour: Blue Odometer: 539138 km

Engine Capacity: 12882 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 295/80R22.5 Rear Tyre Size: 295/80R22.5(D/D)

Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6/66/6 mm

Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6/66/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,512.50	4,939.06	8,573.44	63.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,330.00	1,630.00	55.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,472.50	6,269.06	10,203.44	61.94
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	16,472.50	5,000.00	11,472.50	69.65
+ GST 7.00/7.00% (S\$)	1,153.08	350.00	803.08	69.65
Nett Amount (S\$)	17,625.58	5,350.00	12,275.58	69.65

INSPECTION

Date of Assignment: 21/12/2021

Date Inspected: 24/01/2022 Inspected At: Mah Lian Motor Vehicle Repairer (HQ)
NO. 38 DEFU LANE 9
Singapore 539278

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Feb 2022)	
Parts:	N/A	MITSUBISHI FV51JJD4RDEA 12.9 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XD9398M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent/Twisted	2,861.07 FL	*2,200.83 FL
2	1		*FRONT BUMPER COVER-LH	Cracked/Missing	205.26 FL	*205.26 FL
3	1		*FRONT BUMPER SIDE-LH	Distorted	192.41 FL	*192.41 FL
4	1		*FRONT BUMPER BRACKET-LH	Repair	633.36 FL	*- FL
5	1		*HEADLAMP ASSY-LH	Cracked	1,272.03 FL	*1,272.03 FL
6	1		*HEADLAMP ALUMINIUM BRACKET-LH	Not Necessary	870.06 FL	*- FL
7	1		*HEADLAMP RIM-LH	Cracked	153.63 FL	*153.63 FL
8	1		*FOG LAMP ASSY-LH	Not Necessary	361.67 FL	*- FL
9	1		*FOG LAMP RIM-LH	Cracked	177.34 FL	*177.34 FL
10	1		*FRONT CORNER PANEL-LH	Cracked	1,427.69 FL	*1,427.69 FL
11	1		*FRONT CORNER PANEL RUBBER SEAL-LH	Not Necessary	127.41 FL	*- FL
12	1		*FRONT CORNER PANEL SIGNAL LAMP-LH	Not Necessary	361.67 FL	*- FL
13	1		*FRONT CORNER PANEL SIGNAL LAMP SOCKET-LH	Not Necessary	116.54 FL	*- FL
14	1		*FRONT DOOR LAMP-LH	Broken	361.81 FL	*361.81 FL
15	1		*FRONT DOOR PILLAR-LH	Repair	3,106.53 FL	*- FL
16	1		*FRONT DOOR PILLAR INNER GARNISH-LH	Repair	364.93 FL	*- FL
17	1		*FRONT DOOR PILLAR INNER PANEL-LH	Repair	1,164.51 FL	*- FL
18	1		*STAND PANEL-LH	Repair	2,073.81 FL	*- FL
19	1		*STEP PANEL-LH	Cracked	594.41 FL	*594.41 FL
20	1		*STEP PANEL LOWER-LH	Not Necessary	253.79 FL	*- FL
21	1		*STEP PANEL UNDER COVER-LH	Not Necessary	189.18 FL	*- FL
22	1		*STEP ALLOY TOP-LH	Not Necessary	520.63 FL	*- FL
23	1		*STEP ALLOY LOWER-LH	Not Necessary	393.40 FL	*- FL
24	1		*STEP PANEL REFLECTOR-LH	Not Necessary	233.53 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	18,016.67	6,585.41
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,504.17	1,646.35

Total Parts (\$\$)	13,512.50	4,939.06
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT HEADLAMP,FOGLAMP & REFIT WIRING & REFOCUS ALL LIGHT	New	200.00	30.00
2	LABOUR TO KNOCK & CUT & DISMANTLE & REFIT ALL ABOVE PARTS	New	1,300.00	800.00
3	TO SPRAY & PAINTING AT ACCIDENT AFFECTED AREA	New	980.00	500.00
4	TO RUST PROOFING ON AFFECTED AREA	New	480.00	0.00
Gross Labour Cost (S\$)			2,960.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >