5/4/22, 10:09 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21012955/RQY3N2

Date: 04/05/2022

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00134732100

Claimant Vehicle

GBE1397Z

Insured

GBD5683B

No:

Vehicle No:

Date of Loss:

14/12/2021

Nature of Claim: TP

SNM21D207286/C02/TANKW

JN1SC2F24Z0857249

Yes

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBE1397Z Reg No:

NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 Make & Model:

Reg. Date:

07/09/2015 (Man. Year: 2015)

Engine No: Chassis No: Odometer:

ZD30347696K

177194 km

Colour:

Grey

Engine Capacity: Market Value/New Car Price: 2953 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/70R15C Rear Tyre Size: 165R13(D) Front Left Side: Falken 7 mm Rear Left Side: Falken 5/5 mm Front Right Side: Rear Right Side: Falken 5/5 mm Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,392.74	2,812.51	1,580.23	35.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	1,030.00	310.00	23.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,732.74	3,842.51	1,890.23	32.97
Approved Total (Overridden) (S\$)		3,050.00		
(S\$)	5,732.74	3,050.00	2,682.74	46.80
+ GST 7.00/7.00% (S\$)	401.29	213.50	187.79	46.80
Nett Amount (S\$)	6,134.03	3,263.50	2,870.53	46.80

INSPECTION

Date Inspected:

Date of Assignment: 03/02/2022

Sng Ah Tee Motor & Panel Service Pte Ltd

(Pioneer)

23/12/2021 Inspected At: Blk 3 Pioneer Road North, #01-18

Singapore 628457

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 May 2022)

Parts: NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List) Print Code: (Unsubmitted, no print-code for GBE1397Z)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity:

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Scratched	1,155.10 FN	*945.10 FN
2	1		*FRT CORNER PANEL LH	Bent	436.30 FN	*303.50 FN
3	1		*FRT HEADLAMP LH	Not Necessary	518.50 FN	*- FN
4	1		*FRT DOOR LH	Bent	1,474.10 FN	*1,474.10 FN
5	1		*FRT DOOR HINGE TOP LH	Not Necessary	68.90 FN	*- FN
6	1		*FRT DOOR HINGE BOTTOM LH	Not Necessary	68.90 FN	*- FN
7	1		*FRT DOOR CHECKER (LH)	Not Necessary	48.20 FN	*- FN
8	1		*FRT DOOR LOWER SEAL LH	Necessary	38.10 FN	*38.10 FN
9	1		*FRT DOOR WEATHERSTRIPE LH	Necessary	159.10 FN	*159.10 FN
10	1		*FRT DOOR GLASS REGULATOR LH	Not Necessary	117.60 FN	*- FN
11	1		*FRT DOOR GLASS MOTOR LH	Not Necessary	568.10 FN	*- FN
12	1		*FRT DOOR SIGNAL LAMP LH	Cracked	54.60 FN	*54.60 FN
13	1		*FRT STEP GARNISH LH	Cracked	151.10 FN	*139.40 FN
14	1		*ROC STICKER	Necessary	20.00 FS	*10.00 FS
F=Fra	anchise	part. S=SpcN	ett. N=NettItemDisc.			
				Sub Total (S\$)	4,878.60	3,123.90
			- Nett Item Discount on	485.86	311.39	
				Total Parts (S\$)	4.392.74	2.812.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS	New	650.00	550.00
2	TO PUTTY & RESPRAY PAINTING ON AFFECTED AREAS	S New	500.00	350.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO APPLY ANTI RUST COATING	New	80.00	40.00
5	TO TRANSFER FRT DOOR GLASS LH COMPONENT	New	80.00	60.00
		Gross Labour Cost (S\$)	1,340.00	1,030.00
	Report was unsubmitt	ed during this print-out.		

< END OF ESTIMATES >