

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012956/ETY3N2**Date:** 17/01/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00001592100

Claimant Vehicle No : SMD7623G **Insured Vehicle No :** SMX9764P

Date of Loss: 19/12/2021 Nature of Claim: TP Claim No: SNM21D207407/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD7623G**

Make & Model: VOLKSWAGEN GOLF A7, 1.4 (A) Engine No: CXS222557

Reg. Date: 30/10/2015 (Man. Year: 2014) Chassis No: WVVZZZAUZFW092145

Colour: White Odometer: 92281 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR19 Rear Tyre Size: 225/40ZR19

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,462.69	6,480.94	6,981.75	51.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,420.00	1,810.00	56.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,692.69	7,900.94	8,791.75	52.67
Approved Total (Overridden) (\$\$)		6,300.00		
Nett Amount (\$\$)	16,692.69	6,300.00	10,392.69	62.26

INSPECTION

Date of Assignment: 21/12/2021

Date Inspected: 22/12/2021 Inspected At: Nineteen Autowerks Pte Ltd - Woodlands (HQ)
39 Woodlands Close, MEGA@Woodlands #01-24
Singapore 737856

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2022)
Parts:	143	VOLKSWAGEN GOLF A7 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD7623G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER FOR BUMPER PRIMED	Broken	1,158.63 FL	*1,158.63 FL
2	1	*SET SENSOR BRACKETS	Shorted	221.89 FL	*221.89 FL
3	1	*RETAINER FOR SPOILER	Not Necessary	188.11 FL	*- FL
4	1	*GUIDE PIECE-BUMPER SIDE BRACKET LH	Broken	120.91 FL	*72.00 FL
5	1	*GUIDE PIECE-BUMPER SIDE BRACKET RH	Not Necessary	120.91 FL	*- FL
6	1	*LOWER CONTROL ARM LH	Not Necessary	351.87 FL	*- FL
7	1	*WHEEL BEARING WITH MOUNTI-SOPEX 2019-VGS & NORA	Jammed	562.42 FL	*400.00 FL
8	1	*RADLAGERGAHAUSE-WHEEL BEARING HOUSING	Not Necessary	592.14 FL	*- FL
9	1	*DRIVE SHAFT FRT LH	Not Necessary	2,512.37 FL	*- FL
10	1	*GAS-FILLED SHOCK ABSORBER LH	Bent	531.29 FL	*418.00 FL
11	1	*SUSPENSION STRUT MOUNTING-TOP MTG	Not Necessary	293.61 FL	*- FL
12	1	*BALL BEARING-TOP BEARING LH	Not Necessary	345.71 FL	*- FL
13	1	*TIE ROD LH	Not Necessary	302.45 FL	*- FL
14	1	*TIE ROD END LH	Not Necessary	340.95 FL	*- FL
15	1	*FRT LH FENDER	Dented	869.10 FL	*631.00 FL
16	1	*WHEELHOUSE LINER-FENDER LINER LOWER LH	Torn	284.97 FL	*284.97 FL
17	1	*LH HEADLAMP	Broken	3,818.52 FL	*2,009.00 FL
18	1	*ALLOY WHEEL GALVANO GREY	Cut	1,337.14 FL	*1,100.00 FL
19	1	*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
20	1	*FRONT LH SPLASH SHIELD CLIP	Necessary	50.00 FS	*20.00 FS
21	1	*HEADLAMP CLIP LH	Not Necessary	40.00 FS	*- FS
22	1	*LH WING MIRROR COMPLETE	Broken	850.00 FL	*850.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,942.99	7,195.49
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,480.30	714.55
Total Parts (\$\$)	13,462.69	6,480.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DIAGNOSTIC AND PROGRAMMING	New	350.00	100.00
2	R&R RIM & BALANCE	New	80.00	30.00
3	R&R RHS FRT U/CARRIAGE	New	300.00	150.00
4	WHEEL ALIGNMENT	New	200.00	60.00
5	LABOUR	New	1,200.00	400.00
6	SPRAY PAINT	New	800.00	600.00
7	LABOUR	New	150.00	30.00
8	SPRAY PAINT	New	150.00	50.00
Gross Labour Cost (\$\$)			3,230.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >