

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012967/AGA3Q2**Date:** 17/08/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SNC3280G**Insured Vehicle No :** SFP6D

Date of Loss: 17/12/2021

Nature of Claim: TP Claim No: 8968088925SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNC3280G**

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEMU145639

Reg. Date: 13/10/2021 (Man. Year: 2021)

Chassis No: KMH851CVMU265815

Colour: Grey

Odometer: 1767 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,622.32	773.76	5,848.56	88.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	430.00	2,750.00	86.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,802.32	1,203.76	8,598.56	87.72
+ GST 7.00/7.00% (S\$)	686.16	84.26	601.90	87.72
Nett Amount (S\$)	10,488.48	1,288.02	9,200.46	87.72
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,595.47		

INSPECTION

Date of Assignment: 21/12/2021

Date Inspected: 21/12/2021

Inspected At:

Xin Hua Workshop Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01
Singapore 415933

Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RR BUMPER	Deformed	559.40 FL	*559.40 FL
2	1		*RR BUMPER GARNISH	Cut	296.50 FL	*296.50 FL
3	1		*RR BUMPER TOW COVER	Not Necessary	51.40 FL	*- FL
4	1		*RR BUMPER REFLECTOR LH	Not Necessary	82.30 FL	*- FL
5	1		*RR BUMPER UNDER DUST COVER LH	Not Necessary	105.10 FL	*- FL
6	1		*RR BUMPER UNDER DUST COVER CENTRE	Not Necessary	128.60 FL	*- FL
7	1		*RR BUMPER LOW MLDG CENTRE	Not Necessary	286.90 FL	*- FL
8	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	311.20 FL	*- FL
9	1		*RR BUMPER SIDE RETAINER LH	Necessary	73.80 FL	*73.80 FL
10	1		*RR BUMPER BRACKET LOW LH	Not Necessary	58.20 FL	*- FL
11	1		*RR BUMPER BRACKET UPP LH	Not Necessary	52.90 FL	*- FL
12	1		*RR BUMPER REINFORCEMENT	Not Necessary	387.40 FL	*- FL
13	1		*RR BUMPER REINFORCEMENT STAY LH	Not Necessary	217.40 FL	*- FL
14	2		*RR BUMPER PARKING SENSOR	Not Necessary	348.00 FL	*- FL
15	1		*RR END PANEL	Not Necessary	482.40 FL	*- FL
16	1		*RR FENDER LH	Not Necessary	1,391.80 FL	*- FL
17	1		*RR TAILLAMP PANEL LH	Not Necessary	169.40 FL	*- FL
18	1		*RR TAILLAMP LH	Not Necessary	463.10 FL	*- FL
19	1		*RR TAILGATE LAMP LH	Not Necessary	388.20 FL	*- FL
20	1		*RR RIM LH	Not Necessary	1,291.50 FL	*- FL
21	1		*RR WHEELBEARING LH	Not Necessary	582.40 FL	*- FL
22	10		*RR FENDER INNERSHIELD CLIP	Not Necessary	60.00 FS	*- FS
23	10		*RR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
24	2		*RR TAIL LAMP CLIP	Not Necessary	20.00 FS	*- FS
25	1		*RR TYRE LH	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,167.90	959.70
- List Item Discount on L Items 20.00/20.00% (\$)	1,545.58	185.94
Total Parts (\$)	6,622.32	773.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION , TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,000.00	200.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA	New	1,000.00	200.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	30.00
4	TO CONDUCT ANTI RUST TO TUFF COAT	New	100.00	0.00
5	REMOVE AND REFIX SEAT CUSHION /UPHOLSTERY ROOF LINING SRS SYSTEM TO FACILITATE REPAIRS	New	200.00	0.00
6	TO RESET FAULTY CODE	New	280.00	0.00
7	CONDUCT WATER LEAKAGE TEST	New	60.00	0.00
8	TO REMOVE & REPLACE RR UNDERCARRIAGE PARTS	New	300.00	0.00
9	TO CONDUCT 4 WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			3,180.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >