20/12/2021

Date:

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel: 6721-9016 Fax: 6844-5185

Reg: 201838521G

Vehicle Number: SNC3280G

Vehicle Model: HYUNDAI IONIQ Chassis: KMHC851CVMU265815

Accident Date: 17/12/2021 TP Ins. AXA-INS

Original Reg Date: 13/10/2021

AIG. XIns Torry

		(ESTIMATE		
1	1	RR BUMPER De tomec.	\$559.40	-
2	1	RR BUMPER GARNISH Gt.	\$296.50	~
3	1	RR BUMPER TOW COVER LLE W	\$51.40	X.
4	1	RR BUMPER REFLECTOR LH Nol Men	\$82.30	X.
5	1	RR BUMPER UNDER DUST COVER LH	\$105.10	+
6	1	RR BUMPER UNDER DUST COVER CENTRE	\$128.60	7
7	1	RR BUMPER LOW MLDG CENTRE *** 4-	\$286.90	4.
8	1	RR BUMPER REVERSE SENSOR WIRE HARNESS 💢	\$311.20	+
9	1	RR BUMPER SIDE RETAINER LH	\$73.80	-
10	1	RR BUMPER BRACKET LOW LH 7	\$58.20	+
11	1	RR BUMPER BRACKET UPP LH	\$52.90	×
12	1	RR BUMPER REINFORCEMENT	\$387.40	x
13	1	RR BUMPER REINFORCEMENT STAY LH 2	\$217.40	+
14	2	RR BUMPER PARKING SENSOR	\$348.00	1
15	1	RR END PANEL 7	\$482.40	+
16	1	RR FENDER LH	\$1,391.80	+
17	1	RR TAILLAMP PANEL LH	\$169.40	8
18	1	RR TAILLAMP LH KIN	\$463.10	x
19	1	RR TAILGATE LAMP LH	\$388.20	*
20	1	RR RIM LH	\$1,291.50	X
21	1	RR WHEELBEARING LH	\$582.40	X

0.07		
92970		\$ 7,727.90
743.76	Less 20%	\$ 1,545.58
1,42,10		\$ 6,182.32

		Special Nett		
1	10	RR FENDER INNERSHIELD CLIP MA		60 *
2	10	RR BUMPER CLIP	Ne	_60
3	2	RR TAILLAMP CLIP	12 m	20 *
4	1	RR TYRE LH	11'm	300 +

Labour charge

30

	cident damaged portion,to panel prientate and align repair /replacement	\$	1,000.00	200
Carry out spray painting on	affected area	\$	1,000.00	200
	of electrical component to facilitate selectrical function after repair	\$	120,00	- 30
To conduct anti rust of tuff c	\$	100.00	×	
Remove and refix seat cush to facilitate repairs	\$	200.00	4	
To reset faulty code		\$	280.00	+ +
CONDUCT WATER LEAKA	\$	60.00	+	
TO REMOVE & REPLACE	\$	300.00	X	
TO CONDUCT 4 WHEEL ALIGNMENT			120.00	X

430

Total \$ 9,802.32

GST 7% \$ 686.16

Grand Total \$ 10,488.48

Adrin G p[p]/12/21 02 Days told: 1203.76 (P/P)