

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2331X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DEFORMED	499.90	499.90
1	FRONT BUMPER SIDE BRACKET LH	NECESSARY	82.30	82.30
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT FENDER LH	BENT	945.30	945.30
1	FRONT FENDER (HYBRID) LH	NECESSARY	86.50	86.50
1	FRONT FENDER SHIELD LH	DEFORMED	198.50	198.50
1	FRONT DOOR LH (DENTED)	OLD DAMAGED	1,264.00	-
1	REAR DOOR LH (DENTED)	OLD DAMAGED	1,258.30	-
1	FRONT WHEEL RIM LH	TO REPAIR SEE LABOUR	1,570.55	-
1	WING MIRROR LH (CUT)	OLD DAMAGED	1,390.10	-
1	WING MIRROR OUTER COVER LH (CUT)	OLD DAMAGED	141.90	-
	LESS 25% DISCOUNT		-1,864.84	-458.63
			5,594.51	1,375.87
	NETT ITEMS			
1	REAR DOOR APPS LH (N)	NOT NECESSARY	80.00	-
1	FRONT DOOR COMFORTDELGRO LH (N)	NOT NECESSARY	75.00	-
	LESS 10% DISCOUNT		-15.50	-
			139.50	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT WHEEL RIM LH.		800.00	350.00
	SPRAY PAINTING CHARGE.		1,200.00	500.00
	TUFF KOTE.		100.00	30.00
	TRANSFER OF DOORS.	NOT NECESSARY	240.00	-
	WHEEL ALIGNMENT.		120.00	80.00
			2,460.00	960.00
	GRAND TOTAL		8,194.01	2,335.87

Report Ref No. NS/INC21012978/T1tcn2





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,850.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21012978/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser