

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21012985/AVF3N2**Date:** 24/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900009646
Claimant Vehicle No :	SLU6581Y	Insured Vehicle No :	SLN7307D
Date of Loss:	20/12/2021	Nature of Claim:	TP
		Claim No:	5950119541SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU6581Y	Engine No:	L15B4407813
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11207815
Reg. Date:	08/12/2017 (Man. Year: 2016)	Odometer:	95083 km
Colour:	Bronze		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,751.40	4,147.60	4,603.80	52.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	2,010.00	990.00	33.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,751.40	6,157.60	5,593.80	47.60
Approved Total (Overridden) (S\$)		4,900.00		
Nett Amount (S\$)	11,751.40	4,900.00	6,851.40	58.30

INSPECTION

Date of Assignment:	22/12/2021	Automobile Hub Enterprise 1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT Singapore 417883
Date Inspected:	22/12/2021 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,198.00 FL	*1,198.00 FL
2	1		*TAILGATE I-VTEC EMBLEM	Necessary	65.00 FL	*65.00 FL
3	1		*TAILGATE LOGO	Not Necessary	45.00 FL	*- FL
4	1		*TAILGATE VEZEL EMBLEM	Necessary	58.00 FL	*58.00 FL
5	1		*TAILGATE LAMP N/S	Not Necessary	335.00 FL	*- FL
6	1		*TAILGATE BUZZER	Not Necessary	86.00 FL	*- FL
7	1		*TAILGATE INNER HANDLE	Not Necessary	44.00 FL	*- FL
8	1		*TAILGATE INNER LOCK	Not Necessary	278.00 FL	*- FL
9	1		*TAILGATE LOCK SENSOR	Not Necessary	120.00 FL	*- FL
10	1		*TAILGATE STRIKER	Not Necessary	25.00 FL	*- FL
11	1		*TAILGATE TRIMBOARD	Cracked	455.00 FL	*285.00 FL
12	1		*TAILGATE WEATHERSTRIP	Cut	298.00 FL	*298.00 FL
13	1		*TAILGATE WINDSCREEN MOULDING	Necessary	124.00 FL	*124.00 FL
14	1		*TAILLAMP N/S	Cracked	485.00 FL	*485.00 FL
15	1		*REAR BUMPER	Distorted	986.00 FL	*880.00 FL
16	1		*REAR BUMPER RETAINER	N/s Damaged	98.00 FL	*49.00 FL
17	2		*REAR BUMPER BRACKET	Not Necessary	136.00 FL	*- FL
18	1		*REAR BUMPER SIDE COVER N/S	Distorted	216.00 FL	*216.00 FL
19	1		*REAR BUMPER SIDE REFLECTOR N/S	Cracked	121.00 FL	*121.00 FL
20	2		*REAR BUMPER COVER RETAINER	Not Necessary	104.00 FL	*- FL
21	1		*REAR BUMPER CENTRE LOWER DIFFUSER	Deformed	494.00 FL	*295.00 FL
22	1		*REAR FENDER AIR VENT N/S	Deformed	138.00 FL	*138.00 FL
23	1		*TAILLAMP PANEL OUTER N/S	Repair	385.00 FL	*- FL
24	1		*TAILLAMP PANEL LOWER N/S	Repair	296.00 FL	*- FL
25	1		*REAR FENDER ARCH GARNISH N/S	Deformed	185.00 FL	*185.00 FL
26	2		*TAILGATE HINGE	Not Necessary	130.00 FL	*- FL
27	2		*TAILGATE DAMPER	Not Necessary	398.00 FL	*- FL
28	1		*END PANEL TOP GARNISH	Cracked	252.00 FL	*185.00 FL
29	1		*REAR FENDER INNER TRIM BOARD N/S	Deformed	466.00 FL	*315.00 FL
30	1		*REAR FLOOR PANEL SPONGE	Not Necessary	256.00 FL	*- FL
31	1		*REAR FENDER N/S	Repair	898.00 FL	*- FL
32	1		*END PANEL	Repair	568.00 FL	*- FL
33	8		*REAR FENDER ARCH GARNISH CLIPS N/S	Necessary	44.00 FS	*20.00 FS
34	12		*REAR BUMPER LOWER COWLINGS CLIPS	Necessary	66.00 FS	*30.00 FS
35	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
36	2		*REVERSE SENSOR HOLDER	Not Necessary	64.00 FS	*- FS
37	10		*TAILGATE TRIMBOARD CLIPS	Necessary	55.00 FS	*30.00 FS
38	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
39	1		*END PANEL TOP GARNISH CLIPS (6 Pcs)	Necessary	33.00 FS	*20.00 FS
40	1		*TAILLAMP PANEL SEALANT N/S	Not Necessary	100.00 FS	*- FS
41	10		*REAR BUMPER CLIPS	Necessary	55.00 FS	*30.00 FS
42	1		*REAR BUMPER SIDE COVER CLIPS (12 Pcs)	Necessary	66.00 FS	*10.00 FS
43	8		*REAR FENDER INNER TRIM BOARD CLIPS N/S	Necessary	44.00 FS	*30.00 FS
44	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,700.00	5,127.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,948.60	979.40
Total Parts (\$)	8,751.40	4,147.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW ACCIDENT DAMAGED PORTION.TO PANEL BEAT,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,400.00	900.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	30.00
3	TO REMOVE,REFIT TAILGATE COMPONENTS TO REPLACE TAILGATE,CHECK AND RE-ADJUST CLOSE GAP,ALIGNMENT AND WATER SEEPAGE	New	100.00	80.00
4	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA/PANEL	New	1,200.00	800.00
5	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR WORK	New	150.00	120.00
6	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	80.00
Gross Labour Cost (\$\$)			3,000.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >