

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012987/AQCE2**Date:** 01/11/2022**REFERENCE**

Insured/Claimant:	CHUA SWEE BOON (CAI RUIWEN)	Policy No:	1700063199
Date of Loss:	18/12/2021	Nature of Claim:	OD Claim No: 9924064635SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH7637S	Engine No:	CVN041412
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF4XHA182059
Reg. Date:	11/10/2017 (Man. Year: 2017)	Odometer:	45590 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$94,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	77,038.00	49,082.96	27,955.04	36.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,784.00	13,132.00	10,652.00	44.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	100,822.00	62,214.96	38,607.04	38.29
Approved Total (Overridden) (S\$)		45,800.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	100,222.00	45,200.00	55,022.00	54.90
+ GST 7.00/7.00% (S\$)	7,015.54	3,164.00	3,851.54	54.90
Nett Amount (S\$)	107,237.54	48,364.00	58,873.54	54.90

INSPECTION

Date of Assignment:	22/12/2021	
Date Inspected:	21/12/2021	Inspected At: 24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	17.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	2,111.00 FS	*1,688.80 FS
2	1	*FRONT BUMPER FIXING PARTS (NPA)	Not Necessary	0.00 FS	*- FS
3	2	*FRONT BUMPER SECURING STRIPS	Bent	71.00 FS	*56.32 FS
4	1	*FRONT BUMPER GRILLE - CENTER	Cracked	196.00 FS	*156.40 FS
5	1	*FRONT BUMPER CLOSING ELEMENT LOWER CENTRE	Cracked	210.00 FS	*167.60 FS
6	1	*FRONT BUMPER AIR GUIDE LH	Damaged	63.00 FS	*50.08 FS
7	1	*FRONT BUMPER AIR GUIDE RH	Not Necessary	63.00 FS	*- FS
8	1	*RADIATOR GRILLE	Cracked	1,819.00 FS	*1,455.20 FS
9	2	*AIR GUIDE GRILLE LH / RH	Cut	730.00 FS	*584.00 FS
10	1	*FRONT BUMPER FOAM FILLER	Cracked	124.00 FS	*99.20 FS
11	1	*FRONT BUMPER REINFORCEMENT BEAM	Bent	845.00 FS	*675.60 FS
12	1	*FRONT BUMPER GUIDE SECTION LH / RH	N/S Damaged	74.00 FS	*58.56 FS
13	2	*FRONT BUMPER BRACKET LH / RH	Damaged	456.00 FS	*364.00 FS
14	1	*FRONT BUMPER TOP COVER	Deformed	127.00 FS	*101.60 FS
15	1	*SIGN CAUTION	Necessary	14.00 FS	*10.88 FS
16	1	*STICKER FOR AIR CONDITIONER	Necessary	8.00 FS	*5.68 FS
17	1	*LOCK CARRIER BRACKET	Cracked	137.00 FS	*109.60 FS
18	2	*LOCK CARRIER SUPPORT LH / RH	Damaged	58.00 FS	*44.96 FS
19	1	*HORN HIGH TONE LH	Not Necessary	126.00 FS	*- FS
20	1	*HORN LOW TONE RH	Not Necessary	126.00 FS	*- FS
21	2	*SPRING SHACKLE - LH / RH	Not Necessary	58.00 FS	*- FS
22	2	*FRONT FENDER LH / RH	Repair	1,534.00 FS	*- FS
23	1	*FRONT FENDER ATTACHMENTS PARTS	Not Necessary	202.00 FS	*- FS
24	2	*FRONT FENDER CLOSING ELEMENTS LH / RH	Not Necessary	144.00 FS	*- FS
25	2	*FRONT FENDER BRACKET - LH / RH	Not Necessary	70.00 FS	*- FS
26	2	*FRONT FENDER BRACKET DEFORMATION ELEMENT LH / RH	Not Necessary	98.00 FS	*- FS
27	2	*FRONT FENDER BRACE FRONT LH / RH	Not Necessary	236.00 FS	*- FS
28	1	*WHEEL HOUSING LINER LH	Not Necessary	240.00 FS	*- FS
29	1	*WHEEL HOUSING LINER RH	Not Necessary	241.00 FS	*- FS
30	1	*WHEEL HOUSING LINER ATTACHMENTS PARTS (NPA)	Not Necessary	0.00 FS	*- FS
31	2	*WHEEL SPOILER LH / RH	Damaged	146.00 FS	*58.40 FS
32	2	*WHEEL SPOILER TRIM LH / RH	Not Necessary	71.00 FS	*- FS
33	1	*BONNET	Dented	3,246.00 FS	*2,596.80 FS
34	1	*BONNET ATTACHMENTS PARTS	Not Necessary	412.00 FS	*- FS
35	1	*BONNET LID HINGE LH / RH	Not Necessary	610.00 FS	*- FS
36	1	*BONNET IMPACT PROTECTON CENTRE / LH / RH (3PCS)	Necessary	84.00 FS	*65.68 FS
37	2	*BONNET STRIKER LH / RH	Damaged	100.00 FS	*79.84 FS
38	2	*BONNET LID LOCK	Damaged	427.00 FS	*341.60 FS
39	2	*BOWDEN CABLE CENTRE LH / RH	Damaged	116.00 FS	*92.00 FS
40	1	*BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
41	1	*RELEASE LEVER	Not Necessary	14.00 FS	*- FS
42	1	*LID LOCK CABLE	Not Necessary	74.00 FS	*- FS
43	1	*COVER FOR PLENUM CHAMBER	Not Necessary	97.00 FS	*- FS
44	2	*FLAT CONNECTOR HOUSING	Not Necessary	26.00 FS	*- FS
45	2	*FRONT FENDER FLEDGE COVER LONG LH / RH	Not Necessary	62.00 FS	*- FS
46	2	*FRONT FENDER FLEDGE COVER SHORT LH / RH	Necessary	46.00 FS	*38.08 FS
47	2	*LED HEADLIGHT LH / RH	Cracked	15,386.00 FS	*12,308.80 FS
48	2	*HEADLIGHT POWER MODULE	Not Necessary	1,521.00 FS	*- FS
49	2	*HEADLIGHT CONTROL UNIT	Damaged	1,501.00 FS	*600.40 FS
50	2	*HEADLIGHT HOSE LH / RH	Not Necessary	72.00 FS	*- FS
51	2	*HEADLIGHT COMPENSATING 10MM PC	Not Necessary	160.00 FS	*- FS
52	2	*HEADLIGHT COMPENSATING 0.8MM PC	Not Necessary	83.00 FS	*- FS
53	2	*HEADLIGHT LIFT CYLINDER LH / RH	Not Necessary	420.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
54	2	*HEADLIGHT BRACKET	Not Necessary	12.00 FS	*- FS
55	1	*HEADLIGHT CORRUGATED PIPE	Damaged	93.00 FS	*74.00 FS
56	1	*LOCK CARRIER	Cracked	1,016.00 FS	*812.80 FS
57	2	*LOCK CARRIER SUPPORT	Damaged	76.00 FS	*60.64 FS
58	1	*A/C CONDENSER	Dented	622.00 FS	*497.60 FS
59	1	*A/C PRESSURE SENSOR	Not Necessary	191.00 FS	*- FS
60	1	*A/C VALVE PRESSURE SWITCH	Not Necessary	51.00 FS	*- FS
61	1	*REFRIGERANT LINE	Not Necessary	167.00 FS	*- FS
62	1	*REFRIGERANT LINE	Not Necessary	340.00 FS	*- FS
63	1	*REFRIGERANT LINE	Not Necessary	248.00 FS	*- FS
64	1	*REFRIGERANT LINE BRACKET	Not Necessary	19.00 FS	*- FS
65	1	*ADDITIONAL COOLER FOR COOLANT LOWER CENTRE	Bent	511.00 FS	*408.40 FS
66	1	*COOLER FOR COOLANT	Bent	655.00 FS	*523.60 FS
67	2	*RUBBER BUSH LOWER	Not Necessary	25.00 FS	*- FS
68	6	*COOLANT	Necessary	266.00 FS	*212.64 FS
69	1	*COOLANT HOSE UPPER	Not Necessary	53.00 FS	*- FS
70	1	*COOLANT HOSE	Not Necessary	117.00 FS	*- FS
71	1	*FAN RING 600W	Cracked	267.00 FS	*213.20 FS
72	1	*RADIATOR FAN	Damaged	2,318.00 FS	*1,854.40 FS
73	2	*RADIATOR FAN AIR GUIDE LH / RH BIG	Damaged	56.00 FS	*44.64 FS
74	2	*RADIATOR FAN AIR GUIDE LH / RH SMALL	Damaged	24.00 FS	*18.88 FS
75	2	*AIR GUIDE UPPER / LOWER	Not Necessary	38.00 FS	*- FS
76	1	*INTAKE AIR DUCT RH	Not Necessary	22.00 FS	*- FS
77	1	*AIR GUIDE	Not Necessary	53.00 FS	*- FS
78	1	*INTAKE HOSE	Not Necessary	95.00 FS	*- FS
79	1	*AIR FILTER	Not Necessary	386.00 FS	*- FS
80	1	*INTAKE CONNECTION	Not Necessary	603.00 FS	*- FS
81	1	*CHARGE AIR COOLER	Not Necessary	775.00 FS	*- FS
82	1	*THROTTLE VALVE ADAPTER	Not Necessary	825.00 FS	*- FS
83	1	*NOISE INSULATION	Not Necessary	572.00 FS	*- FS
84	1	*FRONT WINDSCREEN	Cracked	1,125.00 FS	*900.00 FS
85	1	*GEL FOIL FOR RAIN SENSOR	Necessary	137.00 FS	*109.20 FS
86	1	*RETAINING SPRING	Necessary	21.00 FS	*16.56 FS
87	1	*WINDSCREEN PRIMER	Necessary	20.00 FS	*15.76 FS
88	2	*WATER DEFLECTOR LH / RH	Not Necessary	134.00 FS	*- FS
89	1	*WINDOW SLOT SEAL LH / RH	N/S Cut	614.00 FS	*245.20 FS
90	2	*TRIM STRIP FOR WINDOW GUIDE	Not Necessary	514.00 FS	*- FS
91	1	*AIRBAG UNIT FOR STEERING WHEEL	Activated	3,421.00 FS	*2,736.80 FS
92	1	*AIRBAG UNIT FOR PASSENGER SIDE	Activated	4,374.00 FS	*3,499.20 FS
93	2	*HEAD AIRBAG UNIT LH / RH	Activated	3,726.00 FS	*2,980.80 FS
94	1	*CONTROL UNIT FOR AIRBAG	Activated	2,112.00 FS	*1,689.60 FS
95	3	*CRASH SENSOR FOR AIRBAG FRONT (NPA)	Not Necessary	0.00 FS	*- FS
96	1	*CENTRAL PROTECTION	Activated	533.00 FS	*426.00 FS
97	1	*STEERING WHEEL LEATHER	Not Necessary	2,241.00 FS	*- FS
98	1	*DASHBOARD AIR DUCT	Torn	5,289.00 FS	*4,231.20 FS
99	1	*DEFROSTER NOZZLE FOR WINDSCREEN	Damaged	167.00 FS	*133.60 FS
100	1	*GRILLE	Not Necessary	123.00 FS	*- FS
101	1	*MOULDED HEADLINING	Deformed	1,918.00 FS	*1,534.40 FS
102	1	*THREE POINT AUTOMATIC SEAT BELT TENSIONER	Activated	2,206.00 FS	*1,764.80 FS
103	2	*SEAT BELT HEIGHT ADJUSTER	Damaged	342.00 FS	*273.60 FS
104	2	*GRAB HANDLING FOLDING FRONT	Damaged	283.00 FS	*226.40 FS
105	1	*GRAB HANDLING FOLDING LEFT REAR	Damaged	142.00 FS	*113.20 FS
106	1	*GRAB HANDLING FOLDING RIGHT REAR	Damaged	142.00 FS	*113.20 FS
107	2	*A-PILLAR TRIM LH / RH UPPER	Deformed	408.00 FS	*326.40 FS
108	1	*C-PILLAR TRIM LH	Deformed	217.00 FS	*173.20 FS
109	1	*C-PILLAR RH	Deformed	217.00 FS	*173.20 FS
110	1	*FRONT NO. PLATE	Bent	60.00 FS	*60.00 FS
111	1	*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
112	1	*SUNDRIES	Necessary	500.00 FS	*213.44 FS

Report was unsubmitted during this print-out.

11/1/22, 11:47 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
113	1		*SPEAKER RETAINING FRAME - LH (Supplementary)	Damaged	46.00 FS	*40.72 FS
114	1		*AIRBAG ROUND CONNECTOR HOUSING (Supplementary)	Damaged	259.00 FS	*206.80 FS
115	1		*AIRBAG FLATCONTACT HOUSING (Supplementary)	Damaged	186.00 FS	*148.80 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$)	77,038.00 49,082.96
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	700.00	500.00
3	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	New	800.00	0.00
4	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
5	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	400.00	400.00
6	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN	New	200.00	150.00
7	TO REMOVE AND CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING. BOTH CURTAIN AIR BAGS	New	3,600.00	3,600.00
8	TO REMOVE AND RENEW AIRCON CONDENSERS, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. VACUUM AND REGAS	New	1,400.00	1,400.00
9	TO RENEW COOLANT HOSE, THROTTLE BODY AND OTHER ENGINE COMPONENTS	New	780.00	0.00
10	TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDER, BOTH FRONT DOOR AND BOTH UPPER A-PILLAR	New	6,900.00	3,300.00
11	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
12	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	192.00
13	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDER, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. REORGANISE CRASH MANagements COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,000.00	2,500.00
14	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR	New	500.00	250.00
Gross Labour Cost (\$\$)			23,784.00	13,132.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >