

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21012988/KTY3N2**Date:** 11/01/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00148982101

Claimant Vehicle No : SJM8044J**Insured Vehicle No :** GBK7893L

Date of Loss: 17/12/2021

Nature of Claim: TP

Claim No: SNM21D207396/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJM8044J**

Make & Model: MERCEDES-BENZ C180K, 1.8 (A)

Engine No: 27195231131949

Reg. Date: 16/01/2009 (Man. Year: 2008)

Chassis No: WDD2040462A223830

Colour: Metallic Grey

Odometer: 213981 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17

Rear Tyre Size: 225/45R17

Front Left Side: Continental 8 mm

Rear Left Side: Continental 8 mm

Front Right Side: Continental 8 mm

Rear Right Side: Continental 8 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,126.00	2,465.40	4,660.60	65.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,231.00	1,900.00	2,331.00	55.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,357.00	4,365.40	6,991.60	61.56
Approved Total (Overridden) (\$\$)		3,500.00		
Nett Amount (\$\$)	11,357.00	3,500.00	7,857.00	69.18

INSPECTION

Date of Assignment: 21/12/2021

Date Inspected: 27/12/2021 Inspected At:

Lim Yew Boo Spray Paint Co (HQ)
Blk 10 Sin Ming Industrial Estate, #01-10
Singapore 575645

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jan 2022)
Parts:	143	MERCEDES-BENZ C180K 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJM8044J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER SIDE CHROME/RH	Necessary	121.00 F	*121.00 FN
2	1		*REAR DOOR MLDG/RH	Necessary	110.00 F	*110.00 FN
3	1		*REAR DOOR/RH	Bent	2,548.00 F	*2,090.00 FN
4	1		*REAR DOOR WINDOW OUTER CHANNEL/RH	Serviceable	168.00 F	*- FN
5	1		*REAR DOOR WINDOW OUTER TOP CHANNEL/RH	Serviceable	388.00 F	*- FN
6	1		*REAR DOOR WINDOW FRAME GARNISH/RH	Serviceable	148.00 F	*- FN
7	1		*FRONT DOOR MLDG/RH	Necessary	112.00 F	*112.00 FN
8	1		*FRONT DOOR WINDOW OUTER CHANNEL/RH	Serviceable	148.00 F	*- FN
9	1		*FRONT DOOR WINDOW OUTER TOP CHANNEL/RH	Serviceable	348.00 F	*- FN
10	1		*FRONT DOOR WINDOW FRAME GARNISH/RH	Serviceable	128.00 F	*- FN
11	1		*FRONT DOOR RUBBER/RH	Not Necessary	319.00 F	*- FN
12	1		*FRONT DOOR R/H	Repair	2,131.00 F	*- FN
13	1		*FRONT SIDE MIRROR LOWER COVER/RH	Dented/Cut	65.00 F	*65.00 FN
14	1		*FRONT FENDER EMBLEM AVANTGURDE	Necessary	53.00 F	*53.00 FN
15	1		*REAR DOOR RUBBER/RH (50%)	Necessary	339.00 FS	*169.50 FS
					Sub Total (\$\$)	7,126.00 2,720.50
					- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00 255.10
					Total Parts (\$\$)	7,126.00 2,465.40

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS	New	180.00	30.00
2	TO CHECK WATER SEEPAGE	New	80.00	20.00
3	TO CHECK WIRING FUNCTIONS	New	120.00	20.00
4	TO RE-SET ABS SYSTEM & ERASE REGISTERED FAULT	New	150.00	0.00
5	TO TRANSFER DAMAGE DOOR POWER WINDOW MECHANISM RELATED PARTS TO NEW DOOR	New	1,201.00	80.00
6	TO REPAIR,PANEL BEAT ON RIGHT REAR FENDER,RIGHT FRT FENDER,LABOUR TO REPLACE ABOVE MENTIONED PARTS	New	1,000.00	650.00
7	TO PUTTY,PRIMER & SPRAY PAINT ON RIGHT FRT FENDER,FRT DOOR,REAR DOOR,REAR DOOR,REAR FENDER,REAR BUMPER AND RIGHT FRT AFFECTED SIDE MIRROR USING 2K PAINT	New	1,500.00	1,100.00
Gross Labour Cost (\$\$)			4,231.00	1,900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >