

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 9945J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR LIFTLGATE SUPPORT BAR (SN)	TO REPAIR SEE LABOUR	600.00	-
1	REAR LIFTLGATE SUPPORT BAR YELLOW & BLACK REFLECTIVE STICKER (SN)	NECESSARY	100.00	85.00
1	REAR ALUMINIUM LIFTGATE RH HYDRAULIC TRANSVERSE CYLINDER (SMALL)(SN)	NOT NECESSARY	1,500.00	-
1	REAR CENTRE BUMPER ASSY (SN)	BENT	920.00	650.00
1	REAR CENTRE BUMPER YELLOW & BLACK REFLECTIVE STICKER (SN)	NECESSARY	100.00	85.00
1	REAR LH BUMPER ASSY (SN)	BENT	450.00	300.00
1	REAR LH BUMPER YELLOW & BLACK REFLECTIVE STICKER (SN)	NECESSARY	60.00	60.00
2	REAR NUMBER PLATE LAMP (SN)	CUT (1 PC ONLY)	160.00	60.00
1	REAR NUMBER PLATE BRACKET (SN)	BENT	235.00	90.00
1	REAR NUMBER PLATE (SN)	BENT	25.00	25.00
			4,150.00	1,355.00
	<u>LABOUR</u>			
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE.		120.00	30.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		600.00	500.00
	TO PROVIDE LABOUR TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT STRUCTURE CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR LIFTLGATE SUPPORT BAR.		1,000.00	500.00
	TO APPLY ANTI-RUCT CHEMICAL ON REPAIRED AND REPLACED PANEL.		80.00	40.00
			1,800.00	1,070.00
	GRAND TOTAL		5,950.00	2,425.00



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,950.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMR21012991/R1qf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

P

ANG BRYAN TANI

Automotive Assessor / Investigator