

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21012992/AQCN2**Date:** 24/06/2022**REFERENCE**

Insured/Claimant:	TEO KEE HUAT	Policy No:	7210086538	
Date of Loss:	18/12/2021	Nature of Claim:	OD	Claim No: 3557669545SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF2836E		
Make & Model:	AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A)	Engine No:	CZDC41885
Reg. Date:	05/08/2021 (Man. Year: 2021)	Chassis No:	WAUZZZF34M1131576
Colour:	Grey	Odometer:	3883 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$185,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/65R17	Rear Tyre Size:	215/65R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,977.00	5,210.40	10,766.60	67.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,272.00	2,472.00	2,800.00	53.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	21,249.00	7,682.40	13,566.60	63.85
+ GST 7.00/7.00% (S\$)	1,487.43	537.77	949.66	63.85
Nett Amount (S\$)	22,736.43	8,220.17	14,516.26	63.85

INSPECTION

Date of Assignment:	22/12/2021		
Date Inspected:	21/12/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,335.00 FS	*1,068.00 FS
2	1		*FRONT BUMPER CONNECTING PIECE	Not Necessary	145.00 FS	*- FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	414.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LH	Not Necessary	59.00 FS	*- FS
5	1		*FRONT TRIM	Cracked	356.00 FS	*284.40 FS
6	1		*FRONT BUMPER GRILLE-CENTER	Cracked	217.00 FS	*173.20 FS
7	2		*FRONT PARKING AID SENSOR SUPPORT-LH/RH	Not Necessary	50.00 FS	*- FS
8	1		*FRONT BUMPER GRILLE COVER	Not Necessary	51.00 FS	*- FS
9	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	190.00 FS	*- FS
10	1		*FRONT BUMPER SPOILER	Distorted	763.00 FS	*610.00 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	153.00 FS	*- FS
12	1		*FRONT BUMPER TRIM-LH MANHATTAN GREY	Cut	164.00 FS	*130.80 FS
13	1		*FRONT PARKING AID SENSOR SUPPORT OUTER-LH	Not Necessary	25.00 FS	*- FS
14	1		*RADIATOR GRILLE	Cracked	1,928.00 FS	*1,542.40 FS
15	1		*FRONT STRIKER PLATE	Cracked	244.00 FS	*194.80 FS
16	1		*RADIATOR GRILLE COVER	Deformed	244.00 FS	*194.80 FS
17	1		*RADIATOR BRACKET	Not Necessary	41.00 FS	*- FS
18	1		*RADIATOR BRACKET COVER	Not Necessary	56.00 FS	*- FS
19	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	102.00 FS	*- FS
20	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	916.00 FS	*- FS
21	1		*FRONT BUMPER TOP COVER	Not Necessary	123.00 FS	*- FS
22	1		*CAUTION STICKER	Not Necessary	14.00 FS	*- FS
23	1		*AIR COND STICKER	Not Necessary	8.00 FS	*- FS
24	1		*HORN-LH	Not Necessary	137.00 FS	*- FS
25	2		*FRONT PARKING AID SENSOR	Not Necessary	0.00 FS	*- FS
		NPA				
26	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
27	1		*HEADLIGHT MOUNTING-LH	Cracked	118.00 FS	*94.40 FS
28	1		*HEADLIGHT-LH	Not Necessary	5,589.00 FS	*- FS
29	1		*LIFT CYLINDER-LH	Not Necessary	210.00 FS	*- FS
30	1		*LIFT CYLINDER HOSE	Not Necessary	80.00 FS	*- FS
31	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Not Necessary	7.00 FS	*- FS
32	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	240.00 FS	*- FS
33	1		*FRONT WHEEL HOUSING TRIM-LH	Not Necessary	16.00 FS	*- FS
34	2		*FRONT WHEEL ARCH COVER-LH/RH	Necessary	1,072.00 FS	*857.60 FS
35	1		*RADIATOR AIR GUIDE-LH	Not Necessary	38.00 FS	*- FS
36	2		*RADIATOR AIR GUIDE-UPPER/LOWER	Not Necessary	84.00 FS	*- FS
37	1		*FRONT NOISE INSULATION	Not Necessary	397.00 FS	*- FS
38	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
39	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
40	1		*HORN BRACKET-LH	Not Necessary	22.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **15,977.00** **5,210.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
4	TO RESPRAY FRONT BUMPER,FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS	New	3,000.00	1,300.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			5,272.00	2,472.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >