

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21012993/UEA3Q2**Date:** 04/03/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800015419-03
Claimant Vehicle No :	SLC4532Y	Insured Vehicle No :	SLW4814D
Date of Loss:	22/12/2021	Nature of Claim:	TP
		Claim No:	5556458379SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC4532Y	Engine No:	2ZR1766580
Make & Model:	TOYOTA WISH, 1.8 CVT (A)	Chassis No:	JTDGG20W10J004210
Reg. Date:	16/05/2016 (Man. Year: 2016)	Odometer:	85217 km
Colour:	Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,175.57	3,105.52	1,070.05	25.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	1,980.00	1,030.00	34.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,185.57	5,085.52	2,100.05	29.23
Approved Total (Overridden) (S\$)		4,050.00		
(S\$)	7,185.57	4,050.00	3,135.57	43.64
+ GST 7.00/7.00% (S\$)	502.99	283.50	219.49	43.64
Nett Amount (S\$)	7,688.56	4,333.50	3,355.06	43.64
+ Car Rental (4.0 x S\$120.00/day) (S\$)		480.00		
Nett Liability (S\$)		4,813.50		

INSPECTION

Date of Assignment:	22/12/2021		
Date Inspected:	23/12/2021	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	491.90 FL	*491.90 FL
2	10		*REAR BUMPER CLIPS	Necessary	46.00 FL	*46.00 FL
3	2		*REAR BUMPER BRACKET	Repair	96.80 FL	*- FL
4	2		*REAR BUMPER RED REFLECTOR	Not Necessary	107.80 FL	*- FL
5	1		*REAR END PANEL	Dented	453.90 FL	*453.90 FL
6	1		*REAR END PANEL TOP GARNISH	Not Necessary	253.20 FL	*- FL
7	1		*REAR TAILGATE	Dented /Bent	1,477.30 FL	*1,477.30 FL
8	1		*REAR TAILGATE BADGE	Necessary	66.20 FL	*66.20 FL
9	2		*REAR TAILGATE REFLECTOR	Not Necessary	596.40 FL	*- FL
10	1		*REAR TAILGATE WEATHERSTRIP RUBBER	Twisted	302.60 FL	*302.60 FL
11	1		*REAR TAILGATE LOCK	Dented / Jammed	361.60 FL	*361.60 FL
12	1		*REAR TAILGATE LOCK CATCH	Not Necessary	35.30 FL	*- FL
13	2		*REAR BUMPER SIDE RETAINER (WHITE)	Bent	179.80 FL	*179.80 FL
14	1		*REAR BUMPER SIDE RETAINER (BLACK)	Bent	106.40 FL	*106.40 FL
15	1		*REAR WINDSCREEN MOULDING	Necessary	145.40 FL	*145.40 FL
16	1		*REAR NUMBER PLATE CHROME GARNISH	Not Necessary	183.90 FL	*- FL
17	1		*REAR TAILGATE VALUE MATIC EMBLEM	Necessary	45.40 FL	*45.40 FL
18	1		*REAR FENDER (NPA)	Repair	0.00 FL	*- FL
19	1		*ANTENNA SENSOR	Cracked	144.20 FL	*144.20 FL
20	1		*REAR NUMBER PLATE	Serviceable	35.00 FS	*- FS
21	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
22	1		*REAR W/S SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,449.10	4,060.70
- List Item Discount on L Items 25.00/25.00% (\$)	1,273.53	955.18
Total Parts (\$)	4,175.57	3,105.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REAR W/S LABOUR DISMANTLE & REFIX	New	120.00	120.00
2	LABOUR CHARGE	New	1,100.00	800.00
3	SPRAY PAINTING	New	1,500.00	900.00
4	LABOUR TO REMOVE CARPETS ,GARNISHES	New	120.00	80.00
5	WIRING	New	50.00	20.00
6	TUFF COAT	New	120.00	60.00
Gross Labour Cost (\$\$)			3,010.00	1,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >