



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------|-------------------------------|--|
| SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 | | | Ref: CS3/SMO21009033/Atf3e2-1 | |
| | | | Date: 09/02/2022 | |
| | | | Code: SMO | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SKS 391R | Veh. Inspected | SMW 7483T | |
| Policy No. | D21MTPV01004088 | Coverage (\$) | 0.00 | |
| Claim No. | CMTD2102520/RUC | Excess (\$) | 0.00 | |
| Assign From | RUTH CHUA GEK TIANG | Assign Date | 22/12/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | B.M.W. Z4 | c.c | 2171 | |
| Engine No. | HIDDEN | Year of Reg. | 2006 | |
| Chassis No. | WBABT12050LR02142 | Colour | BLACK | |
| Odometer | 199184 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 225/40 R18 | HAIDA | 6 mm | |
| L/H Front Tyre | 225/40 R18 | HAIDA | 6 mm | |
| R/H Rear Tyre | 225/40 R18 | HAIDA | 6 mm | |
| L/H Rear Tyre | 225/40 R18 | HAIDA | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 20/08/2021 | Inspection Date | 30/08/2021 | |
| Survey held at | EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 5 Working Days | |