



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2201528

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 17/03/2022
Reference CC4/FCI21013001/Aea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMA 4621Y

Insured Veh. YN 967R

Claim No. D21003489MCVT

Policy No.

Accident Date 21/12/2021

Inspection Date 22/12/2021

Description	Total
Survey Inspection	308.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	308.00
GST (7%)	21.56
Grand Total	329.56

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21013001/Aea3q2	
			Date: 17/03/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 967R	Veh. Inspected	SMA 4621Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	D21003489MCVT	Excess (\$)	0.00
	Assign From	KAREN	Assign Date	22/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	GK81202011	Colour	SILVER
	Odometer	68743 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/12/2021	Inspection Date	22/12/2021
	Survey held at	ADVANCE AUTO GARAGE 10 KAKI BUKIT ROAD 2 #03-01 FIRST EAST CENTRE SINGAPORE 417868		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 4621Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,050.50	1,050.50
2	FRONT BUMPER SIDE HOLDER @\$35.00	NOT NECESSARY	70.00	-
1	FRONT BUMPER REINFORCEMENT	DENTED	420.90	397.20
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	152.40	-
1	FRONT GRILLE	CRACKED	363.30	363.30
1	FRONT GRILLE CHROME MOULDING	CUT	292.60	292.60
1	FRONT GRILLE LOGO	NECESSARY	48.20	48.20
1	BONNET	DENTED	1,080.10	1,080.10
1	BONNET LOCK	NOT NECESSARY	135.20	-
1	BOOTLID WEATHERSTRIPE	NOT NECESSARY	75.10	-
2	HEADLAMP @\$2128.70	N/S CRACKED	4,257.40	2,128.70
	LESS 20% DISCOUNT		-	-1,072.12
			7,945.70	4,288.48
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	30.00	-
1	FRONT NUMBER PLATE HOLDER (SN)	NOT NECESSARY	30.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT GRILLE CLIPS (SN)	NECESSARY	20.00	20.00
			110.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	400.00
	SPRAY PAINTING.		800.00	400.00
	WIRING.		50.00	30.00
			1,650.00	830.00
	GRAND TOTAL		9,705.70	5,168.48



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,100.00
---	--	--	-----------------

Report Ref No. CC4/FCI21013001/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 4621Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMA 4621Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

