11/30/22, 2:59 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21013005/R1QY3Q2

30/11/2022 Date:

Engine No:

Chassis No:

Odometer:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMHCSNW00010612100

Claimant Vehicle

SLG7507E

Insured

SMP6973P

No:

Vehicle No:

Nature of Claim: TP

Date of Loss:

11/12/2021

Claim

SNM21D207280/C02/LEEPG

2NR8676563

129620 km

NRE1610021906

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLG7507E Reg No:

TOYOTA COROLLA AXIO, 1.5 CVT ABS D/AIRBAG Make & Model:

2WD (A)

Reg. Date: 12/10/2016 (Man. Year: 2016)

Colour:

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 185/60 R15 Rear Tyre Size: Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm Front Right Side: Rear Right Side: Firenza 6 mm Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,965.67	2,083.46	1,882.21	47.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,200.00	600.00	33.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,765.67	3,283.46	2,482.21	43.05
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	5,765.67	2,600.00	3,165.67	54.91
+ GST 7.00/7.00% (S\$)	403.60	182.00	221.60	54.91
Nett Amount (S\$)	6,169.27	2,782.00	3,387.27	54.91

INSPECTION

Date of Assignment: 22/12/2021

NO 4 JLN BESUT 22/12/2021 Inspected At: Date Inspected:

Repairer:Lion City Rental (jalan Lam Huat) (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Nov 2022)

Parts: TOYOTA COROLLA AXIO 1.5 CVT ABS D/AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List) Print Code: (Unsubmitted, no print-code for SLG7507E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	850.00 FL	*552.25 FL
2	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	289.00 FL	*- FL
3	1		*FRONT BUMPER SPONGE	Not Necessary	60.00 FL	*- FL
4	1		*F/R HEADLAMP ASSY	Broken	950.00 FL	*700.00 FL
5	1		*FRONT BONNET	Bent	1,200.00 FL	*809.70 FL
6	1		*FRONT BONNET INSULATOR	Not Necessary	260.40 FL	*- FL
7	1		*FRONT SUPPORT PANEL	Not Necessary	895.50 FL	*- FL
8	1		*F/R FENDER	Buckled	676.00 FL	*676.00 FL
9 F=Fra	1 inchise	part S=SpcNe	*SET FRONT BUMPER CLIPS ett. L=ListItemDisc.	Necessary	80.00 FS	*30.00 FS
		pain o opoin		Sub Total (S\$)	5,260.90	2,767.95
	- List Item Discount on L Items 25.00/25.00% (S\$)			1,295.23	684.49	
				Total Parts (S\$)	3,965.67	2,083.46
			Report was unsubmitted	d during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	our Items						
1	TO LABOUR CHARGE FOR REMOVING FRONT BONNET, SUPPORT PANEL, FRONT BUMPER ASSY OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS	New	900.00	600.00			
2	TO RESPRAY FRONT BONNET ,SUPPORT PANEL AND FRONT BUMPER	New	900.00	600.00			
	Gross Labor	ur Cost (S\$)	1,800.00	1,200.00			
	Report was unsubmitted during this print-out.						

< END OF ESTIMATES >