

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21013007/VPA3Q2**Date:** 08/04/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SHD4699S**Insured Vehicle No :** SLJ9592D

Date of Loss: 20/12/2021

Nature of Claim: TP Claim No: 3686470809SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD4699S**

Make & Model: HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)

Engine No: G4LEKU415032

Reg. Date: 30/10/2020 (Man. Year: 2019)

Chassis No: KMHC851CVLU191613

Colour: Blue

Odometer: 128877 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: West Lake 5 mm

Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm

Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,252.20	1,252.20	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	1,240.00	260.00	17.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,752.20	2,492.20	260.00	9.45
+ GST 7.00/7.00% (S\$)	192.65	174.45	18.20	9.45
Nett Amount (S\$)	2,944.85	2,666.65	278.20	9.45
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.19/day) (S\$)		375.57		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,194.22		
Global Sum Settlement (S\$)		3,100.00		

INSPECTION

Date of Assignment: 22/12/2021

Date Inspected: 22/12/2021 Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -FR BUMPER	Cut	430.90 FL	*430.90 FL
2	1		*BRACKET -FR BUMPER SIDE RH	Necessary	35.00 FL	*35.00 FL
3	10		*BUMPER COVER CLIP FRONT	Necessary	22.00 FL	*22.00 FL
4	1		*MOULDING FRONT BUMPER CTR	Distorted	368.50 FL	*368.50 FL
5	1		*PANEL FENDER RH	Dented	588.80 FL	*588.80 FL
6	1		*MOULDING -FRONT BUMPER RH	Scratched	93.45 FL	*93.45 FL
7	1		*EMBLEM -BLUE DRIVE RH	Necessary	26.60 FL	*26.60 FL
					Sub Total (\$\$)	1,565.25
					- List Item Discount on L Items 20.00/20.00% (\$\$)	313.05
					Total Parts (\$\$)	1,252.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	700.00
2	SPRAYPAINT CHARGE	New	600.00	500.00
3	CHECK ALL LIGHTING	New	50.00	20.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	20.00
Gross Labour Cost (\$\$)			1,500.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >