

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21013014/RNY3Q2**Date:** 04/11/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00130282100

**Claimant Vehicle No :** SLQ9763R **Insured Vehicle No :** SJU9191T

Date of Loss: 17/12/2021 Nature of Claim: TP Claim No: SNM21D207371/C02/TANKL

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLQ9763R**

Make & Model: TOYOTA PRIUS HYBRID, 1.8 CVT (A) Engine No: 2ZRS058555

Reg. Date: 28/07/2017 (Man. Year: 2017) Chassis No: JTDKB3FUX03562369

Colour: White Odometer: 427638 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,977.12	2,014.27	1,962.85	49.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,450.00	1,350.00	48.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,777.12</b>	<b>3,464.27</b>	<b>3,312.85</b>	<b>48.88</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,750.00</b>		
<b>(S\$)</b>	6,777.12	2,750.00	4,027.12	59.42
<b>+ GST 7.00/7.00% (S\$)</b>	474.40	192.50	281.90	59.42
<b>Nett Amount (S\$)</b>	<b>7,251.52</b>	<b>2,942.50</b>	<b>4,309.02</b>	<b>59.42</b>

**INSPECTION**

Date of Assignment: 22/12/2021

Date Inspected: 22/12/2021 Inspected At: Lion City Rentals Pte Ltd (HQ)  
No 4 Jln Besut  
Singapore 619557

Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL**Manager:** HUEY YON

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Nov 2022)
<b>Parts:</b>	144	TOYOTA PRIUS HYBRID 1.8 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ9763R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BACK DOOR	Repair	922.50 FL	*- FL
2	1		*REAR BACK DOOR CENTRE GARNISH COVER	Deformed	850.00 FL	*850.00 FL
3	1		*REAR BACK DOOR TOYOTA EMBLEM	Necessary	45.80 FL	*45.80 FL
4	1		*REAR BACK DOOR HYBRID EMBLEM	Necessary	52.30 FL	*52.30 FL
5	1		*REAR BACK DOOR PIRUS EMBLEM	Necessary	45.80 FL	*45.80 FL
6	1		*REAR BACK DOOR LOCK	Not Necessary	447.40 FL	*- FL
7	1		*REAR BACK DOOR LOCK CATCH	Not Necessary	24.60 FL	*- FL
8	1		*REAR BACK DOOR WEATHERSTRIP	Necessary	356.80 FL	*356.80 FL
9	1		*REAR BUMPER	Deformed	423.90 FL	*423.90 FL
10	1		*REAR BUMPER CENTER PAD	Deformed	552.30 FL	*552.30 FL
11	1		*REAR BUMPER RH RETAINER	Not Necessary	112.70 FL	*- FL
12	1		*REAR BUMPE REINFORCEMENT	Bent	318.80 FL	*318.80 FL
13	1		*REAR BUMPER LOWER COVER	Not Necessary	303.90 FL	*- FL
14	1		*REAR BUMPER TOW COVER	Not Necessary	35.90 FL	*- FL
15	1		*REAR END PANEL	Not Necessary	356.80 FL	*- FL
16	1		*SET BUMPER AND END PANEL CLIPS	Necessary	80.00 FS	*30.00 FS
17	1		*SET REVERSE SENSOR	Not Necessary	260.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,189.50</b>	<b>2,675.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,212.38	661.43
<b>Total Parts (\$\$)</b>	<b>3,977.12</b>	<b>2,014.27</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO LABOUR CHARGE FOR REMOVING REAR BACK DOOR ,REAR END PANEL ,SPARE TYRE PANEL ,REAR BUMPER AND REAR BUMPER REINFORCEMENT OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS .ALSO TO REPLACE R/R FENDER	New	1,000.00	600.00
2	TO RESPRAY REAR BUMPER ,REAR BACK DOOR ,CENTER GARNISH ,REAR BUMPER ,END PANEL ,SPARE TYRE PANEL ,BOTH SIDE EXTENSION FILLERS AND R/R FENDER	New	1,000.00	700.00
3	TRANSFER DOOR MECHANISM TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS	New	200.00	0.00
4	TO CONDUCT A STANDARD OF OPEARTING PROCEDURES POST SCAN TEST AS AREQUIREMENTS FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	300.00	150.00
5	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS	New	300.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,800.00</b>	<b>1,450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >