

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21013016/UPS3Q2**Date:** 01/03/2023**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBB7993D**Insured Vehicle No :** SGM6585M

Date of Loss: 15/12/2021

Nature of Claim: TP

Claim No: 9087530244SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBB7993D**

Make & Model: HONDA ANF125MSS A, 125cc

Engine No: NF125MME5000655

Reg. Date: 06/08/2007 (Man. Year: 2007)

Chassis No: NF125MM5000655

Colour: Black

Odometer: 49528 km

Engine Capacity: 125 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 80/90-17

Rear Tyre Size: 80/90-17

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,884.80	1,605.70	3,279.10	67.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	350.00	680.00	66.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,914.80	1,955.70	3,959.10	66.94
Approved Total (Overridden) (S\$)		1,550.00		
Nett Amount (S\$)	5,914.80	1,550.00	4,364.80	73.79
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		1,700.00		

INSPECTION

Date of Assignment: 15/12/2021

Date Inspected: 23/12/2021 Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FORK INNER TUBES	Serviceable	280.00 FL	*- FL
2	2		*FORK INNER TUBES	Not Necessary	290.00 FL	*- FL
3	1		*FORK UNDER BRACKET	Not Necessary	185.00 FL	*- FL
4	1		*FRONT SPORT RIM	Not Necessary	280.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	42.00 FL	*- FL
6	1		*FRONT RIM BEARING	Not Necessary	38.00 FL	*- FL
7	1		*SET FRONT SIGNAL	Not Necessary	130.00 FL	*- FL
8	1		*SET SIDE MIRROR (O/S)	Cut	96.00 FL	*96.00 FL
9	1		*HANDLE -BAR	Not Necessary	80.00 FL	*- FL
10	1		*HANDLE -BAR ENDS (O/S)	Scratched	95.00 FL	*30.00 FL
11	1		*SET HAND GRIP	Not Necessary	50.00 FL	*- FL
12	1		*HANDLE -BAR INNER COVER	Not Necessary	128.00 FL	*- FL
13	1		*HEADLAMP	Cracked	160.00 FL	*160.00 FL
14	1		*FRONT FOOTREST BRACKET	Not Necessary	55.00 FL	*- FL
15	1		*FRONT FOOTREST RUBBERS (O/S)	Torn	56.00 FL	*56.00 FL
16	1		*BRAKE PEDAL	Bent	42.00 FL	*42.00 FL
17	2		*REAR FOOTREST	Serviceable	76.00 FL	*- FL
18	1		*REAR FOOTREST BRACKET	Not Necessary	130.00 FL	*- FL
19	1		*REAR TAILLAMP	Cracked	88.00 FL	*88.00 FL
20	1		*REAR FENDER	Distorted	68.00 FL	*68.00 FL
21	1		*REAR SPORT RIM	Not Necessary	380.00 FL	*- FL
22	1		*REAR RIM SHAFT	Not Necessary	68.00 FL	*- FL
23	1		*REAR SWING ARM	Repair	450.00 FL	*- FL
24	1		*REAR ABSORBER	Not Necessary	320.00 FL	*- FL
25	1		*MAIN STAND	Not Necessary	48.00 FL	*- FL
26	1		*SIDE STAND	Not Necessary	58.00 FL	*- FL
27	1		*EXHAUST ASSY	Dented	428.00 FL	*350.00 FL
28	1		*EXHAUST PROTECTOR	Bird Droppings	98.00 FL	*98.00 FL
29	1		*BASKET	Repair	58.00 FL	*- FL
30	1		*FAIRING ASSY	Cracked	485.00 FL	*485.00 FL
31	1		*SET NUMBER PLATE	Rear Bent	38.00 FS	*10.00 FS
32	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
33	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
34	1		*SET STEERING CONE BEARING	Not Necessary	85.00 FS	*- FS
35	1		*REAR BOX	Damaged	200.00 FS	*180.00 FS
36	1		*REAR BOX BRACKET	Not Necessary	100.00 FS	*- FS
37	1		*SET STICKER	Necessary	90.00 FS	*90.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,361.00	1,753.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	476.20	147.30
Total Parts (\$\$)	4,884.80	1,605.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING (LOD)	New	50.00	50.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO REPAIR BODY FRAME	New	480.00	0.00
4	TO PROVIDE LABOUR	New	420.00	300.00
Gross Labour Cost (\$\$)			1,030.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >