4/11/23, 1:03 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21013018/VPA3Q2

11/04/2023 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7210128266 **Claimant Vehicle**

GBK3790B Insured Vehicle No: YQ4830J No:

Date of Loss: 16/12/2021 Nature of Claim: TP Claim No: 1665838898SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK3790B**

NISSAN NV350, 2.5 (A) Make & Model: Engine No: YD25062376B

Reg. Date: 29/06/2020 (Man. Year: 2019) Chassis No: JN1MC2E26Z0031834

48125 km Colour: Odometer: Grey

Engine Capacity: 2488 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C 195 R15C Rear Tyre Size: Rear Left Side: Grenlander 7 mm Front Left Side: Grenlander 7 mm Front Right Side: Grenlander 7 mm Rear Right Side: Grenlander 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,408.65	3,050.32	3,358.33	52.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,560.00	1,680.00	51.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,648.65	4,610.32	5,038.33	52.22
Approved Total (Overridden) (S\$)		3,700.00		
(S\$)	9,648.65	3,700.00	5,948.65	61.65
+ GST 8.00/8.00% (S\$)	771.89	296.00	475.89	61.65
Nett Amount (S\$)	10,420.54	3,996.00	6,424.54	61.65
+ Loss of Use (4.0 x S\$80.00/day) (S\$)		320.00		
+ D	oc/Search Fee (S\$)	7.45		
	Nett Liability (S\$)	4,323.45		

INSPECTION

Date of Assignment: 22/12/2021

Efficient Motor & Engineering Works Pte Ltd (HQ) Date Inspected: 22/12/2021 Inspected At: 37 Loyang Way

Singapore 508734

Estimated Period of Repair: 4.0 days

Adjuster: Thevan Thomas Karthikesavan Manager: **CHEW HSIAO TONG** NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	667.20 FL	*667.20 FL
2	3		*REAR BUMPER SIDE CLIP LH	Necessary	36.30 FL	*36.30 FL
3	1		*TAILGATE	Dented	2,280.00 FL	*1,900.00 FL
4	1		*TAILLAMP LH	Cracked	224.80 FL	*224.80 FL
5	1		*TAILGATE LOGO	Necessary	115.20 FL	*115.20 FL
6	1		*TAILGATE EMBLEM NV350 URBAN	Necessary	156.00 FL	*101.30 FL
7	1		*REAR END PANEL OUTER	Repair	360.90 FL	*- FL
8	1		*REAR FENDER LH	Repair	1,793.40 FL	*- FL
9	1		*TAIL LAMP PANEL LH	Repair	465.30 FL	*- FL
10	1		*REAR REINFORCEMENT PANEL INNER LH	Serviceable	464.10 FL	*- FL
11	1		*TAILGATE FEMALE DOVETAIL	Serviceable	85.70 FL	*- FL
12	1		*TAILGATE MALE DOVETAIL	Serviceable	49.60 FL	*- FL
13	1		*SEALANT	Necessary	80.00 FS	*50.00 FS
14	1		*70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
15	1		*PAN PACIFIC METAL PLATE	Necessary	80.00 FS	*40.00 FS
16	1		*REVERSE SENSOR	Cut	200.00 FS	*200.00 FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	7,078.50	3,354.80
			- List Item Discount on L Ite	ms 10.00/10.00% (S\$)	669.85	304.48
				Total Parts (S\$)	6,408.65	3,050.32
			Report was unsubmitted during the	nis print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CUT /WELD REAR FENDER PANEL BEAT & INNER PANEL,REMOVE & REPLACE DAMAGED PARTS	New	1,400.00	700.00
2	TO APPLY ANTI RUST ,COAT AND TUFF KOTE REPAIRED AREAS	New	100.00	30.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	120.00	30.00
4	TO REMOVE & REPLACE REVERSE SENSOR	New	120.00	30.00
5	TO REMOVE AND REFIT TAILGATE WINDSCREEN TO FACILITATE REPAIR	New	150.00	120.00
6	TO TRANSFER TAILGATE PARTS AND MECHANISM TO NEW TAILGATE	New	150.00	50.00
7	TO SPRAY PAINTING FOR REAR LH PORTIONS & AFFECTED AREAS	New	1,200.00	600.00
	Gross Labour Cost (S\$)		3,240.00	1,560.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >