



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2204432

INV Date 20/07/2022

Reference CC4/LPC21013028/Rga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKG 6339S

Insured Veh. XE 1092S

Claim No.

Policy No. Z/21/VC00/109915

Accident Date 21/12/2021

Inspection Date 27/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC21013028/Rga3q2 Date: 20/07/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 1092S	Veh. Inspected	SKG 6339S	
Policy No.	Z/21/VC00/109915	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	GERALD	Assign Date	22/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E200 SEDAN AVG	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WDD2130802A700282	Colour	GREY	
Odometer	47756 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45 R18	PIRELLI	6 mm	
L/H Front Tyre	245/45 R18	PIRELLI	6 mm	
R/H Rear Tyre	245/45 R18	PIRELLI	6 mm	
L/H Rear Tyre	245/45 R18	PIRELLI	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	21/12/2021	Inspection Date	27/12/2021	
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 6339S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH/R DISC WHEEL (SN)	SCRATCHED	779.44	690.65
1	REAR WINDSHIELD (SN)	NECESSARY	1,518.87	1,518.87
1	REAR WINDSHIELD SEAL (SN)	NOT NECESSARY	41.06	-
2	GLAZING REPAIR KIT (SN)	NECESSARY	320.22	320.22
1	RH/R FENDER (SN)	BENT	2,579.50	2,579.50
1	RH/R WHEEL ARCH COVER (SN)	NOT NECESSARY	195.30	-
1	RH/R FENDER AIR FLAP (SN)	NOT NECESSARY	27.17	-
1	ADHESIVE SEALANT (SN)	NECESSARY	780.70	780.70
1	TWO-COMPONENT ADHESIVE (SN) (ADDITIONAL)	NECESSARY	102.50	102.50
1	SEAM SEAL SEALANT (SN) (ADDITIONAL)	NECESSARY	105.52	105.52
1	INSULATION (SN) (ADDITIONAL)	NECESSARY	18.35	18.35
1	TANK FILLER RECESS (SN) (ADDITIONAL)	CRACKED	254.58	254.58
			6,723.21	6,370.89
	<u>LABOUR</u>			
	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.		380.00	380.00
	REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR DR REPL.		300.00	240.00
	RENEW REAR WINDSHIELD .		560.00	560.00
	SUPPLY & TRANSFER 1PC REAR WINDSHIELD SOLAR FILM .		300.00	300.00
	SUPPLY & TRANSFER 1PC REAR RIGHT RIM .		60.00	60.00
	INSPECT & CONDUCT WHEEL ALIGNMENT .		540.00	540.00
	REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR.		1,440.00	960.00
	REMOVE & REPLACE REAR RIGHT FENDER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.		4,800.00	3,840.00
	RESPRAY REAR RIGHT DOOR ,REAR RIGHT FENDER ,REAR BUMPER & REAR END PANEL.		2,400.00	2,100.00
			10,780.00	8,980.00
	GRAND TOTAL		17,503.21	15,350.89

Report Ref No. CC4/LPC21013028/Rga3q2



RECOMMENDED COST OF REPAIRS			15,350.89
------------------------------------	--	--	------------------

Report Ref No. CC4/LPC21013028/Rga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKG 6339S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKG 6339S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

