

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21013032/R1TF3E2

Date: 21/01/2022

REFERENCE

Insured/Claimant: SHENG YEE ZHER (SHENG YIZHE) Policy No: 1800122921
Date of Loss: 21/12/2021 Nature of Claim: OD Claim No: 4590546592SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EK52H**
Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11AA4180
Reg. Date: 13/11/2018 (Man. Year: 2018) Chassis No: GF7W0600200
Colour: Grey Odometer: 47812 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$91,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18
Front Left Side: Arivo 6 mm Rear Left Side: Arivo 6 mm
Front Right Side: Arivo 6 mm Rear Right Side: Arivo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,896.00	2,005.83	890.17	30.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	1,380.00	450.00	24.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,726.00	3,385.83	1,340.17	28.36
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	4,126.00	2,785.83	1,340.17	32.48
+ GST 7.00/7.00% (S\$)	288.82	195.01	93.81	32.48
Nett Amount (S\$)	4,414.82	2,980.84	1,433.98	32.48

INSPECTION

Date of Assignment: 23/12/2021
Date Inspected: 27/12/2021 Inspected At: Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FACE, RR BUMPER	Cut	1,018.00 F	*1,018.00 FL
3	1		*EXTENSION, RR BUMPER	Cut	292.00 F	*292.00 FL
4	1		*REINFORCEMENT, RR BUMPER, LH	Not Necessary	79.00 F	*- FL
5	1		*BRKT, R/BMPR FACE SIDE, LH	Not Necessary	12.00 F	*- FL
6	1		*MOUDLING, RR BUMPER, LH	Not Necessary	106.00 F	*- FL
7	1		*LAMP ASSY, COMB, RR LH	Cracked	603.00 F	*603.00 FL
8	1		*REFLECTOR, TAIL LAMP, LH	Not Necessary	100.00 F	*- FL
9	1		*LAMP ASSY, TAIL, LH	Scratched	506.00 F	*506.00 FL
10	1		*MOULDING, RR WHEEL ARCH, LH	Necessary	160.00 F	*160.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,896.00	2,599.00
- List Item Discount on L Items 0.00/23.00% (S\$)	0.00	593.17
Total Parts (S\$)	2,896.00	2,005.83

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER, REAR LH FENDER	New	900.00	450.00
2	SPRAY PAINT FOR REAR BUMPER, REAR LH FENDER	New	700.00	700.00
3	REMOVE & INSTALL PARKING SENSOR	New	80.00	80.00
4	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
5	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	120.00	120.00
Gross Labour Cost (\$\$)			1,830.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >